

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
2040 South Pacheco  
Santa Fe, NM 87505

Form C-141  
Revised March 17, 1999  
JUL 24 2007  
OCD-ARTESIA  
Submit Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company <i>Burnett Oil Co Inc</i>	Contact <i>Belton Mathews</i>
Address <i>PO Box 188 Loco Hills NM 88255</i>	Telephone No. <i>505-677-2313</i>
Facility Name <i>Grayburg Jackson San Andres Unit</i>	Facility Type <i>water Flood/Injection Station</i>

Surface Owner <i>BLM</i>	Mineral Owner <i>BLM</i>	Lease No.
-----------------------------	-----------------------------	-----------

#### LOCATION OF RELEASE

Unit Letter	Section <i>13</i>	Township <i>T17S</i>	Range <i>R30E</i>	Feet from the	North/South Line	Feet from the	East/West Line	County <i>Eddy</i>
-------------	----------------------	-------------------------	----------------------	---------------	------------------	---------------	----------------	-----------------------

#### NATURE OF RELEASE

Type of Release <i>Injection Leak</i>	Volume of Release <i>20 BBLS</i>	Volume Recovered <i>0</i>
Source of Release <i>Produced water</i>	Date and Hour of Occurrence <i>7-17 8:30 AM</i>	Date and Hour of Discovery <i>8:50 AM</i>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

*Leak in weld on pipe  
Mix surrounding soil with Contaminated Area*

Describe Area Affected and Cleanup Action Taken.\*

*Down Main Road to Water Flood Plant  
Into small Ravine Raking & mixing soil*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Belton Mathews</i>	OIL CONSERVATION DIVISION	
Printed Name: <i>Belton Mathews</i>	Approved for District Supervisor: <i>[Signature]</i>	
Title: <i>District Superintendent</i>	Approval Date: <i>JUL 25 2007</i>	Expiration Date:
Date: <i>7-24-07</i> Phone: <i>505-677-2313</i>	Conditions of Approval:	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary