

Submit 3 Copies To Appropriate District Office
 District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 1301 W. Grand Ave., Artesia, NM 88210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 May 27, 2004

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

WELL API NO.	30-015-33450
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	Center Sixteen SWD
8. Well Number	1
9. OGRID Number	14049
10. Pool name or Wildcat	SWD; Delaware

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/> SWD	
2. Name of Operator Marbob Energy Corporation	
3. Address of Operator PO Box 227, Artesia, NM 88211-0227	
4. Well Location Unit Letter <u>K</u> : <u>2640</u> feet from the <u>South</u> line and <u>2640</u> feet from the <u>West</u> line Section <u>16</u> Township <u>25S</u> Range <u>28E</u> NMPM <u>Eddy</u> County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 2991' GL	
Pit or Below-grade Tank Application <input type="checkbox"/> or Closure <input type="checkbox"/>	
Pit type <u> </u> Depth to Groundwater <u> </u> Distance from nearest fresh water well <u> </u> Distance from nearest surface water <u> </u>	
Pit Liner Thickness: <u> </u> mll Below-Grade Tank: Volume <u> </u> bbls; Construction Material <u> </u>	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPL <input type="checkbox"/>		SUBSEQUENT REPORT OF: REMEDIAL WORK <input checked="" type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> P AND A <input type="checkbox"/> CASING/CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: Mechanical Integrity Test <input checked="" type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

5/22/07 - MIRU WOU. Run GR/IB to 2742' & tag pkr. RIH w/ CIBP @ set @ 2730'. Bleed pressure off tbg. Nipple down well head. Nipple up BOP.

5/23/07 - Test stack to 700#. Release pkr & POOH. POOH w/ tbg & found 1 bad collar. Laid down 3 jts tbg & pkr. PU & MU new nickel plated 5 1/2" x 2 7/8" 10K PLS pkr w/ Otis 1.875 X profile nipple & pump out plug on bottom of pkr. Ran 85 jts tbg. Hydrotest to 3000# below slips. Tested OK. Set pkr @ 2748'. Release on/off tool. Circ hole w/ 2% HCL wtr w/ pkr fluid. Latch back onto pkr. Nipple down BOP. Set slips. Pack off well head. Test casing side to 320# for 30 minutes. Tested good. (See chart attached). RU kill truck on tbg & pump out the plug @ 2600#.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOC guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Diana J. Briggs TITLE Production Analyst DATE 5/29/07

Type or print name Diana J. Briggs E-mail address: production@marbob.com Telephone No. (505) 748-3303

For State Use Only

APPROVED BY: Gerry Guye TITLE Deputy Field Inspector DATE AUG 13 2007

Conditions of Approval (if any):

Gerry Guye
 Deputy Field Inspector
 District II - Artesia