

## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

## BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.

Director

Oil Conservation Division

A CARL PARK A CARLOS OF THE SAME OF THE SA

20-Aug-07

LCX ENERGY, LLC
110 NORTH MARIENFELD SUITE 200
MIDLAND TX 79701

LOV NO. 02/1907

**LETTER OF VIOLATION - Inspection** 

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

## INSPECTION DETAIL SECTION

M-2-18S-23E NICHOLS 1823 No.021 30-015-34857-00-00 Inspection \*Significant Corrective Type Inspection Inspector Violation? Inspection No. Non-Compliance? Date Action Due By: 08/20/2007 Routine/Periodic Ron Harvey Yes No 9/21/2007 iREH0723245440 Violations Emergency/Temporary Pits Well active. Status reads N instead of A. Well sign wrong. Well number on sign is 2-1 instead of Comments on Inspection: 21. Drilling pit open and contains fluids/solids. Pt fence ok. Pit liner breached in violation of Rule 50. Photos taken. **1625 STATE COM No.161** A-16-16S-25E 30-015-35412-00-00 Inspection \*Significant Corrective **Type Inspection** Violation? Inspector Inspection No. Date Non-Compliance? Action Due By: 08/20/2007 Routine/Periodic Yes iREH0723253270 Ron Harvey No 9/21/2007

Violations

Emergency/Temporary Pits

Comments on Inspection: Well completed. Well head installed with no flowline, well not producing

Well completed. Well head installed with no flowline, well not producing. Drilling pit open. Pit fence ok. Pit liner breached on south side of horseshoe in violation of Rule 50. Photos taken.

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely,

Artesia OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data \*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas