

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

SEP 20 2007  
OCD-ARTESIA

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

30-015-26150

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	HARVEY E. YATES COMPANY	Contact	Clay Stevens or Jen Serrano
Address	PO Box 1933, Roswell 88202-1933	Telephone No.	(505) 623-6601
Facility Name	SOUTH TAYLOR 13 FEDERAL #4	Facility Type	Tank Battery

Surface Owner	USA	Mineral Owner	BLM	Lease No.	NMN2537
---------------	-----	---------------	-----	-----------	---------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	13	18S	31E	1650'	SOUTH	660'	EAST	EDDY COUNTY, NM

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE



Type of Release	Minor	Volume of Release	appx 28 bbls	Volume Recovered	bbls
Source of Release	oil tank	Date/Hour of Release	6/3/07	Date/Hour Discovered	6/4/07
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required		If YES, To Whom? Paul Evans, BLM		
By Whom?	Jen Serrano	Date and Hour 6/4/07 8:25 am			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		If YES, Volume Impacting the Watercourse. n/a		

If a Watercourse was Impacted, Describe Fully.\*  
n/a

Describe Cause of Problem and Remedial Action Taken.\*  
Lost pressure on heater treater, water was sent to oil tank causing the oil to run over and onto location.

Describe Area Affected and Cleanup Action Taken.\*  
90% of spill onto location, a small puddle about 10 yds off location. Vacuumed up as much possible. Used 10 gallons microblaze to 550 gal. water. Soil samples taken and analysis submitted to the OCD-Artesia office.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Jen Serrano		Approved by District Supervisor: 	
Title: Engineering Tech		Approval Date: SEP 20 2007 Expiration Date:	
E-mail Address: jserrano@heycoenergy.com		Conditions of Approval:	
Date: 09/19/07 Phone: (505)623-6601		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary