

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505



WELL API NO. 30-015-32773
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name REDDTAILED HAWK 10-H
8. Well Number 1
9. OGRID Number 148111
10. Pool name or Wildcat WILLOW LAKE, DELAWARE, SW

4. Well Location BHL D 546 North 329 West SL Unit Letter C : 780 feet from the NORTH line and 2610 feet from the WEST line Section 10 Township 25S Range 28E NMPM EDDY County
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 2969 GR

Pit or Below-grade Tank Application <input type="checkbox"/> or Closure <input type="checkbox"/>
Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____
Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
OTHER: RECOMPLETE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE ~~REPAIRING~~ OPNS ☒ P AND A ☐
CASING/CEMENT JOB ☒
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. (see attached).

09/01/2007 MIRU
09/05/2007 Wash & ream to TD 6865'
09/06/2007 Run 4-1/2" 11.6#, N-80 liner from 4357' (TOL) to 6864' (float shoe)
09/07/2007 Cement liner w/219 sxs Class H (TOC 4358)
10/05/2007 MIRU Completion Unit
10/10/2007 Perforate as follows: (5226.82' - 6720') 5226.82 - 3 shots; 5369.24 - 3 shots; 5567.68 - 4 shots; 5761.83 4 shots;
5957.38 - 5 shots; 6130.86 - 5 shots; 6325.27 - 6 shots; 6524.02 - 6 shots; 6720 - 6 shots.
10/11/2007 Acidize with 6000 glas 15% Nefe HCl acid
10/13/2007 Frac w/ 7500 lbs 20/40 proppant & 200,880 lbs 16/30 proppant with 3867 bbls fluid
10/14/2007 Clean out after frac

Return well to production

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Martha C. Howard TITLE Staff Regulatory Analyst DATE 10-18-2007

Type or print name Martha C. Howard

E-mail address:

Telephone No. 281-618-4887

For State Use Only

APPROVED BY: FOR RECORDS ONLY TITLE _____ DATE OCT 22 2007
Conditions of Approval (if any):