District I
1625 N French Dr , Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 For drilling and production facilities, submit to appropriate NMOCD District Office.
For downstream facilities, submit to Santa Fe office

Form C-144 June 1, 2004

Pit or Below-Grade Tank Registration or Closure

	k covered by a "general plan"? Yes No or below-grade tank Closure of a pit or below-grade	
Operator Yates Petroleum Corporation Telephone 505-748-4500 e-mai Address. 105 South 4 th Street, Artesia, N M 88210 Facility or well name BiplaneUnit #6 API # 30-005-63979 U/L or Qtr/Qtr N County Chaves Latitude 33 78984 Longitude 10 Surface Owner Federal State Private Indian	N Sec <u>16 T 6S R 26E</u>	OCT 16 2007 OCD-ARTESIA
Pit Type Drilling Production Disposal	Below-grade tank Volume:bbl Type of fluid Construction material Double-walled, with leak detection? Yes	
Wellhead protection area (Less than 200 feet from a private domestic water source, or less than 1000 feet from all other water sources)	Yes No	(20 points) (0 points) XXXX
Distance to surface water (horizontal distance to all wetlands, playas, irrigation canals, ditches, and perennial and ephemeral watercourses)	Less than 200 feet 200 feet or more, but less than 1000 feet 1000 feet or more	(20 points) (10 points) XXXX (0 points)
	Ranking Score (Total Points)	10 POINTS
If this is a pit closure: (1) Attach a diagram of the facility showing the pit's relationship to other equipment and tanks (2) Indicate disposal location (check the onsite box if you are burying in place) onsite offsite offsite. If offsite, name of facility NA (3) Attach a general description of remedial action taken including remediation start date and end date (4) Groundwater encountered No Yes If yes, show depth below ground surface ft and attach sample results (5) Attach soil sample results and a diagram of sample locations and excavations Additional Comments Closure workplan for drilling pit. The drilling pit contents will be mixed to stiffen the pit contents. An encapsulation trench will be excavated and lined with a 12 mil synthetic liner on former drilling pit site. Drilling pit contents will then be emplaced into the encapsulation trench. A 20 mil synthetic liner will then be placed over the pit contents with a minimum of a 3' over lap of the underlying trench areas. The encapsulation trench will then be backfilled to grade using a minimum of 3' of clean soil and like material. A one call and 48 hour notice will be provided to the Oil Conservation Division before pit closure actions begin. Pit Closure actions to begin by NA. Ending date NA. See Attached. Stipulations		
I hereby certify that the information above is true and complete to the best of m	y knowledge and belief I further certify that the abo	
Date 10/12/2007 Printed Name/Title Mike Stubblefield / Environmental Regulatory Agent Your certification and NMOCD approval of this application/closure does not relieve the operator of liability should the contents of the pit or tank contaminate ground water or otherwise endanger public health or the environment. Nor does it relieve the operator of its responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Approval Printed Name/Title Compliance Officer	Signature Demy Juy	OCT 1 8 2007


Stipulations for closing Of Pit

Samples are to be obtained from pit area and analysis submitted to NMOCD prior to back filling. Notify NMOCD 24 hours prior to obtaining samples.

If burial trench is to be constructed in the pit area, samples are to be obtained from that area and analyses submitted to NMOCD prior to lining the pit, but after contaminated soils have been excavated from trench area.

Notify NMOCD 24 hours prior to beginning closure.

DATA INDICATES THIS AREA TO BE WATER SENSITIVE. As a condition of approval, if during pit construction, water is encountered or if water seeps into pits after construction the **OCD MUST BE CONTACTED IMMEDIATELY**



g at the second	New Mexico Office of the State Engineer POD Reports and Downloads BIPLANE UNIT #6 30-005-63979	
Township: 05S	Range: 26E Sections:	
NAD27 X:	Y: Zone: Search Radius:	
County: Bas	in: Number: Suffix:	
Owner Name: (First)	(Last) ONon-Domestic ODomestic © All	
POD / Surface Data Report Avg Depth to Water Report Water Column Report		
	Clear Form iWATERS Menu Help	
,		

AVERAGE DEPTH OF WATER REPORT 10/12/2007

Record Count: 1