

District I  
1625 N. French Dr., Hobbs, NM 88201  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Revised October 10, 2003

Form C-141

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

## Release Notification and Corrective Action

## OPERATOR

☒ Initial Report ☐ Final Report

Name of Company YATES PETROLEUM CORPORATION	OGRID Number 25575	Contact SHERRY BONHAM
Address 105 S 4 <sup>TH</sup> STREET	API Number 30 015 32709	Telephone No. 505.748.1471
Facility Name MUCHO LUCK BBW FEDERAL COM	Facility Type TANK BATTERY	
Surface Owner FEDERAL	Mineral Owner FEDERAL	Lease No.

## LOCATION OF RELEASE

Unit Letter L	Section 27	Township 16S	Range 27E	Feet from the 1980	North/South Line SOUTH	Feet from the 660	East/West Line WEST	County EDDY
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.89163 Longitude 104.27258

## NATURE OF RELEASE

Type of Release PRODUCED WATER	Volume of Release 15 B/PW	Volume Recovered 5 B/PW
Source of Release WATER TANK	Date and Hour of Occurrence 11/23/07 PM	Date and Hour of Discovery 11/23/07 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	



If a Watercourse was Impacted, Describe Fully.\*  
N/A

Describe Cause of Problem and Remedial Action Taken.\*  
WATER TANK RAN OVER, SITUATION CORRECTED.

Describe Area Affected and Cleanup Action Taken.\*  
APPROXIMATELY 15' X 15' (225 ft<sup>2</sup>) AREA AFFECTED. RELEASED FLUIDS WERE CONTAINED INSIDE THE DIKE AT THE BATTERY. FREE LIQUIDS RECOVERED BY VACUUM TRUCK. RELEASE IMPACTED SOILS HAVE BEEN EXCAVATED AND HAULED TO DISPOSAL FACILITY. PRELIMINARY SOIL SAMPLES OBTAINED AND SENT TO A LABORATORY FOR ANALYSES. SITE TO BE REMEDIATED IN ACCORDANCE WITH NMOCD GUIDELINES.

Depth to Ground Water: >50' and <100'; Wellhead protection? NO; Distance to surface water: >1000'. SITE RANKING: 10.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Sherry Bonham	Approved by District Supervisor: 	
Title: Environmental Regulatory Agent	Approval Date: DEC 7 2007	Expiration Date:
E-mail Address: sherryb@ypc nm.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: December 5, 2007	Phone: 505.748.1471	

\* Attach Additional Sheets If Necessary