

Summary Report

Tom Brandt
Marshall & Winston Inc.
P.O. Box 50880
Midland, Tx, 79710

Report Date: December 12, 2007

Work Order: 7121020

Project Name: Dublin 23 Fed #3 **30-015-35729**

Sample	Description	Matrix	Date Taken	Time Taken	Date Received
144960	N 1/2 Main Pit Floor/Wall	soil	2007-12-04	13:00	2007-12-10
144961	S 1/2 Main Pit Floor/Wall	soil	2007-12-04	13:30	2007-12-10

Sample: 144960 - N 1/2 Main Pit Floor/Wall

Param	Flag	Result	Units	RL
Chloride		105	mg/Kg	5.00

Sample: 144961 - S 1/2 Main Pit Floor/Wall

Param	Flag	Result	Units	RL
Chloride		78.4	mg/Kg	5.00