

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

DEC 27 2007
OCD-ARTESIA

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

X Initial Report

Final Report

Name of Company Yates Petroleum Corporation	Contact Mike Stubblefield
Address 105 South 4 th Street, Artesia, N.M. 88210	Telephone No. 505-7484500 505-513-1712
Facility Name CatchlawHuisache Battery 30-015-26913	Facility Type Tank Battery

Surface Owner State	Mineral Owner State	Lease No. E-2781
---------------------	---------------------	------------------

LOCATION OF RELEASE

Unit Letter H	Section 2	Township 20s	Range 24e	Feet from the FNL	North/South Line FNL	Feet from the FWL	East/West Line FWL	County Eddy
------------------	--------------	-----------------	--------------	----------------------	-------------------------	----------------------	-----------------------	----------------

Latitude 32.60474 Longitude 104.55197

NATURE OF RELEASE

Type of Release Produced Water & Oil.	Volume of Release 285 bbls Produced Water 5 bbls oil	Volume Recovered 280 bbls PW. 4.5 bbls Oil
Source of Release Water transfer pump.	Date and Hour of Occurrence 12/16/2007 am.	Date and Hour of Discovery 12/16/2007 am
Was Immediate Notice Given? Yes X No Not Required	If YES, To Whom? After hours OCD voice mail box.	
By Whom? Jerry Fanning	Date and Hour 12/22/2007 12 40pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully *

Describe Cause of Problem and Remedial Action Taken.*

2" line downstream of check valve and ball valve on discharge line off of the water transfer pump busted.

Describe Area Affected and Cleanup Action Taken *

The impacted area was the bermed area of the tank battery and the pasture directly behind the tank battery. Soil samples will be taken for analytical from the impacted area. Soil samples will be sent to a second party lab & analysis ran for TPH, B-tex & chlorides. If the initial analytical results find the TPH & B-tex to be over the RRAL. A work plan will be submitted to OCD for the correction of the hydrocarbons. When Analytical results reflect the TPH & B-tex to be under the RRAL The Chlorides will be documented. A final C-141 form will be submitted to the OCD requesting closure for the release that occurred on 12/16/2007.

Depth to ground water > 100', Wellhead protection area > 1000', Distance to surface water body > 1000' Site ranking 0

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: *Mike Stubblefield*

Printed Name: Mike Stubblefield

Title: Environmental Regulatory Agent

E-mail Address: mikes@ypcnm.com

Approved by District Supervisor *[Signature]*

Approval Date:

Expiration Date:

Conditions of Approval:

Attached ☐

Date: 12/26/2007

Phone: 505 748 4500

cc: Jennifer Palma

Master file 12/27/02-n.s.