

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

30-015-26930

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company <i>Pogo Producing Co.</i>	Contact <i>Pat Ellis</i>
Address <i>P.O. Box 10340 Midland, TX 79702</i>	Telephone No. <i>(432) 685-8100</i>
Facility Name <i>D. Maggio Tank Battery</i>	Facility Type <i>TANK BATTERY</i>
Surface Owner	Mineral Owner
Lease No. <i>NM-1800</i>	

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<i>J</i>	<i>16</i>	<i>26S</i>	<i>29E</i>	<i>1650</i>	<i>South</i>	<i>1693</i>	<i>East</i>	<i>Eddy</i>

Latitude *32 02 24.2 N* Longitude *103 59 10.9 W*

#### NATURE OF RELEASE

Type of Release <i>Oil</i>	Volume of Release <i>40 BBLs</i>	Volume Recovered <i>35 BBLs</i>
Source of Release <i>TANK BATTERY</i>	Date and Hour of Occurrence	Date and Hour of Discovery
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>12-7-07 11:45 AM</i> <i>NMOCD GERRY GUYE</i> <i>BLM TERRY</i>	<i>12-7-07 12:15 PM</i> <i>12-7-07 12:15 PM</i>
By Whom? <i>Johnny Burnett</i>	Date and Hour <i>12-7-07 12:15 PM</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

*NA*

Describe Cause of Problem and Remedial Action Taken.\*

*Oil production being produced to oil tank, tank filled up and equalizing line plugged up and allowed 40 BBLs of oil to overflow.*

Describe Area Affected and Cleanup Action Taken.\*

*Vacuum truck was called and recovered 35 BBLs of oil. Backhoe was utilized to pick up and remove saturated soil. Highlander Environmental will take soil samples and review for closure workplan.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Patrick L. Ellis</i>	OIL CONSERVATION DIVISION	
Printed Name: <i>PATRICK L. ELLIS</i>	Approved by District Supervisor: <i>[Signature]</i>	
Title: <i>EHS Supervisor</i>	Approval Date: <i>JAN 23 2008</i>	Expiration Date:
E-mail Address: <i>ellispl@pogoproducing.com</i>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <i>1-22-08</i> Phone: <i>(432) 685-8100</i>		

\* Attach Additional Sheets If Necessary