

015-33881

Oil Conservation District
1301 W Grand
Artesia, NM 88210

JAN 30 2008
OCD-ARTESIA

Attention Ron Harvey
Inspection # iREH0727842262
Chi Operating
Munchkin Fed # 006

This is to notify you that we have resolved the issues on this location.

We corrected all leaks, steamed cleaned the tanks, shoveled all contaminated gravel out of berm area, steamed off the 20 mil liner. There are no breaches in the liner. Spread out clean gravel over liner.

Thank you,
Sonny Mann

Chi Operating
432-634-7062

Inspected 1-10-08. Remediation work to be completed.

Inspected 1-31-08 Remediation ~~work~~ completed, compliance resolved

Roadrunner Environmental
P.O. Box 1238
Carlsbad N.M. 88220

Oil Conservation Division
1301 W. Grand
Artesia N.M. 88210

Attention: Mr. Ron Harvey
Inspection No. iREH0727842262
Chi Operating Inc.
MUNCHKIN FEDERAL NO.006

Roadrunner is submitting a plan of action to remediate the area inside the firewalls surrounding the tank battery.

This battery is built on top of a 20 mill liner that runs under the tanks and over the firewalls. I believe the liner has held the hydrocarbons on location as designed.

- 1st) Tighten all bolts, piping, and capping any open ended pipes to stop all seepage
- 2nd) Steam clean tanks and all piping on battery
- 3rd) Carefully shovel all contaminated gravel from top of liner
- 4th) Wash down liner with clean well water and suck up with vac truck
- 5th) Spread clean gravel over liner

All contaminated material picked up on location will be hauled to a properly licensed disposal facility and disposed of in accordance with O.C.D. and B.L.M. requirements.

Please feel free to contact me if you have any questions or concerns.

Thank You,

Mike Felkins
Roadrunner Env.
Off. 505-887-6067
Cell. 505-361-2774
