District I - (505) 393-6161 PO Box 1980 Hobbs, NM 88241-1980 District II - (505) 748-1283 1301 W Grand Ave Artesia, NM 88210 District III - (505) 334-6178 1000 Rio Brazos Road Aztec, NM 87410 <u>District IV</u> - (505) 827-7131

1/28/08

State of New Mexico

Energy Mineral and Natural Resources Department Oil Conservation Division 1220 South St. Francis Drive Santa Fe, New Mexico 87505 (505) 476-3440

JAN 3 1 2008 OCD-ARTESIA Originated 2/13/97 Submit 2 copies to

Form C-141

Appropriate District Office in accordance with Rule 116 on back side of form

14021				Release Notification and Co			rrective Action			Initial Report		Final Report	
Name Con													
Marathon Oil Company						Jerry Harrison							
Addiess							elephone No						
·							75-457-2621 ext. 121 or 575-365-5863						
'							entral Battery						
Surface Owner Mineral Owner							Lease No						
STATE							E 10083 API# 3001527168						
LOCATION OF RELEASE													
Unit Letter	Section	Township	Range	Feet from the	North/South								
D	36	20\$	24E	, cor morri and	110111111000111	Line	1 000, 110111 1110		001 2.110	County	Edd	dv	
NATURE OF RELEASE													
Type of Release							Volume of Release Volume Recovered						
produced water							28 bbl				20bbl		
Source of Release							Date of Occurrence	Hour	of Occurren	ice D	Date of Discovery		
Hole in Pipe line							01/03/08	4	:00am		01/03/08	10:00 AM	
Was Immediate Notice Given?							S, To Whom?						
							Mike Bratcher Date of Notification					late and a	
By Whom?							01/03/08				Hour of Notification 2:10 PM		
Jerry Harrison Was a Watercourse Reached?							If YES, Volume Impacting the Watercourse						
Yes Yes No													
If a watercourse was Impacted, Describe Fully (Attach Additional Sheets If Necessary)													
						N/A							
Describe Caus	e of Problem	and Remedial	Action Take	n (Attach Addition	al Sheets if Nece	essary)							
1 .	-	tigation inc	licated th	at the cause	of the leak	was c	lue to corrosio	on in the	e steel li	ne. T	The corroded	d line section	
was replac							и						
Describe Area Affected and Cleanup Action Taken (Attach Additional Sheets if Necessary)													
The spill occured within a dike. The impacted area, about 15' x21', was cleaned up using a vacuum truck. Since this battery is													
located over an old drill pit, additional remediation, if any, will be done during final closure of the facility.													
I hereby certify	that the infor	mation given at	ove is true a	and complete to the	best of my know	wledge a	and understand tha	t pursuant	to NMOCD	rules a	nd regulation all o	perators are required	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulation all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by													
												amination that pose a sibility for compliance	
with any other f					in addition, Nivic	OD acc	epiance of a C-141	r report doe	ss not renev	re the o	perator or respon	Sibility for compliance	
							C	DIL CON	ISERV	1017	NOISIVIQ		
Signaturi							_			4			
Approved of Mence French													
Printed Name	J. Har	rison			District Supervisor								
Title Production Supervisor							Approval Date Expiration Date						
Date Phone							ditions of Approval				Attached		
1/28	3/08		5	75-457-2621	evt 121		FEB 4		NR				

575-457-2621 ext. 121

2008