

Report Date: December 14, 2007
3327

Work Order: 7121028
Fairway- Midnight Matador A #2

Page Number: 1 of 2
Eddy County, NM

Summary Report

Gary Miller
Highlander Environmental Services
1910 N. Big Spring Street
Midland, TX, 79705

Report Date: December 14, 2007

Work Order: 7121028



30-015-35619

Project Location: Eddy County, NM
Project Name: Fairway- Midnight Matador A #2
Project Number: 3327

Sample	Description	Matrix	Date Taken	Time Taken	Date Received
144995	NE 2'	soil	2007-12-04	00:00	2007-12-10
144996	NW 2'	soil	2007-12-04	00:00	2007-12-10
144997	SE 2'	soil	2007-12-04	00:00	2007-12-10
144998	SW 2'	soil	2007-12-04	00:00	2007-12-10
144999	Center 2'	soil	2007-12-04	00:00	2007-12-10

Sample: 144995 - NE 2'

Param	Flag	Result	Units	RL
Chloride		1720	mg/Kg	2.00

Sample: 144996 - NW 2'

Param	Flag	Result	Units	RL
Chloride		1860	mg/Kg	2.00

Sample: 144997 - SE 2'

Param	Flag	Result	Units	RL
Chloride		577	mg/Kg	2.00

Sample: 144998 - SW 2'

Param	Flag	Result	Units	RL
Chloride		1210	mg/Kg	2.00

Sample: 144999 - Center 2'

TraceAnalysis, Inc. • 6701 Aberdeen Ave., Suite 9 • Lubbock, TX 79424-1515 • (806) 794-1296

This is only a summary. Please, refer to the complete report package for quality control data.

Accepted for record
NMOC

FEB 26 2008

Dehydration to Rock - will cap w/20 Mil & Backfill

Report Date: December 14, 2007
3327

Work Order: 7121028
Fairway- Midnight Matador A #2

Page Number: 2 of 2
Eddy County, NM

Param	Flag	Result	Units	RL
Chloride		207	mg/Kg	2.00