

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

MAR 24 2008

Form C-141  
Revised October 10, 2003

OCD-ARTESIA  
Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR ☐ Initial Report ☒ Final Report

Name of Company	CBS Operating Corp.	Contact	M. A. Sirgo, III
Address	POB 2236 Midland TX 79702	Telephone No.	432/685-0878
Facility Name	North Square Lake Unit 24	Facility Type	Producer well; wellhead
Surface Owner	Bogle LTD Co.	Mineral Owner	
		Lease No.	LC-960971

301504912

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	29	16S	31E	660	north	1980	east	Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	Volume Recovered
Source of Release	Stuffing box leak	Date and Hour of Occurrence	Date and Hour of Discovery
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?		Date and Hour	
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

NA



Describe Cause of Problem and Remedial Action Taken.\*

Leaking stuffing box.  
Repair stuffing box.

Describe Area Affected and Cleanup Action Taken.\*

Remove oil and contaminated soil. Haul contaminated soil to Lea Land Inc. landfill. See attached. Replace affected area with clean dirt.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: M. A. Sirgo, III	Approved by District Supervisor: 		
Title: Engineer	Approval Date: 3-24-08	Expiration Date:	
E-mail Address: mastres@aol.com	Conditions of Approval: N/A	Attached <input type="checkbox"/>	
Date: March 19, 2008	Phone: 432/685-0879		

\* Attach Additional Sheets If Necessary

## **CBS Operating Weights Statement - Total Landfilled**

<i>Receive Date</i>	<i>Manifest Number</i>	<i>Lease Name</i>	<i>Weight (lbs.)</i>	<i>Weight (Tons)</i>
2/12/2008	48738	NSL Unit # 24	85,700	42.85
2/12/2008	48739	NSL Unit # 24	87,500	43.75
2/12/2008	48740	NSL Unit # 24	85,640	42.82
2/12/2008	48741	NSL Unit # 24	94,520	47.26
2/12/2008	48742	NSL Unit # 24	88,340	44.17
TOTALS:			441,700	220.85
			lbs	tons

**Lea Land Landfill New Mexico**

Mile Market # 64 US Highway 62/180

30 miles East of Carlsbad, NM \* (505) 887-4048

PHONE (575) 393-2326 • 101 E. MARLAND • HOBBS, NM 88240

ANALYTICAL RESULTS FOR  
CBS OPERATING  
ATTN: TIM HOUGHTALING  
P.O. BOX 2236  
MIDLAND, TX, 79702  
FAX TO: (432) 685-1945

RECEIVED  
By \_\_\_\_\_  
Date: 02/11/08

Receiving Date: 02/12/08  
Reporting Date: 02/21/08  
Project Owner: MANNY SIRGO  
Project Name: NOT GIVEN  
Project Location: NOT GIVEN

Sampling Date: 02/11/08  
Sample Type: SOIL  
Sample Condition: COOL & INTACT  
Sample Received By: ML  
Analyzed By: CK/HM

LAB NUMBER	SAMPLE ID	GRO	DRO	CI*
		(C <sub>6</sub> -C <sub>10</sub> ) (mg/kg)	(>C <sub>10</sub> -C <sub>28</sub> ) (mg/kg)	(mg/kg)
ANALYSIS DATE		02/12/08	02/12/08	02/12/08
H14245-3	NORTH SQUARE LAKE UNIT 24	61.9	581	1060
Quality Control		562	382	500
True Value QC		500	500	500
% Recovery		112	76.6	100
Relative Percent Difference		6.1	4.5	<0.1

**METHODS:** TPH GRO & DRO: EPA SW-846 8015 M; Cl<sup>-</sup>: Std. Methods 4500-Cl<sup>-</sup>B

\*Analysis performed on a 1:4 w:v aqueous extract.

\* Amended Report

*Clyde Keane*  
Chemist

02/21/08  
Date

H14245CTCL1 CBS

PLEASE NOTE **Liability and Damages.** Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise. Results relate only to the samples identified above. This report shall not be reproduced except in full with written approval of Cardinal Laboratories.