



PHONE (575) 393-2326 • 101 E. MARLAND • HOBBS, NM 88240

ANALYTICAL RESULTS FOR
LCX ENERGY
ATTN: JOHN LOWERY
110 N. MARIENFELD, SUITE #200
MIDLAND, TX 79701
FAX TO: (432) 687-2521, (575) 622-0233
& (575) 578-0180

Receiving Date: 05/07/08
Reporting Date: 05/07/08
Project Number: 92
Project Name: 1625 STATE
Project Location: EDDY COUNTY, NM

Analysis Date: 05/07/08
Sampling Date: 05/07/08
Sample Type: SOIL
Sample Condition: INTACT
Sample Received By: ML
Analyzed By: KS

30-015-35414

C-9-16-25

LAB NUMBER	SAMPLE ID	Cl ⁻ (mg/kg)
H14761-1	NORTH FLOOR	80
H14761-2	SOUTH FLOOR	64
H14761-3	NORTH WALL	16
H14761-4	SOUTH WALL	16
H14761-5	EAST WALL #1	64
H14761-6	EAST WALL #2	64
H14761-7	WEST WALL #1	64
H14761-8	WEST WALL #2	96
Quality Control		500
True Value QC		500
% Recovery		100
Relative Percent Difference		< 0.1

METHOD: Standard Methods 4500-Cl-B


Note: Analyses performed on 1:4 w:v aqueous extracts.

Kirstin Dupudis
Chemist

05/08/08
Date

H14761 LCX

PLEASE NOTE Liability and Damages Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise. Results relate only to the samples identified above. This report shall not be reproduced except in full with written approval of Cardinal Laboratories.



Page _____ of _____

PRIORITY OF ALL!!