




GRAPHIC CONTROLS CORPORATION
BUFFALO, NEW YORK

30min MIT CBS
5/29/08
Loco H-11 A-7
BR 2221

NOON

6 P.M.

MIDNIGHT

6 A.M.

CBS Operating

Loco Hills A #7

Hole in Tubing above slips on
surface pulled well & Fixed.