District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV

**Energy Minerals and Natural Resources** 

JUN 06 2008

Form C-141 Revised October 10, 2003

Oil Conservation Division 1220 South St. Francis Dr.

OCD-ARTES Pubmit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back

1220 S. St. Fra	ncis Dr., Sant	a Fe, NM 8750	5	S	anta ]	Fe, NM 875	505				side of for	
SEBOSISS LSEBOSISS	51099		Rele	ase Notifi	catio	on and C	orrective A	ction		<del></del>		
NSEB0818550546			260007			<b>OPERATOR</b>			X Initial Report			
Name of Company St. Mary Land & Exploration Co.						Contact To	Final Rep					
Address 3300 N. A St. Bldg 7, Suite 200, Midland, TX 79705						Telephone No. 432-688-1773						
Facility Na	me Parkv	vay Delawar	e Unit #70	)3		Facility Typ	e Injection W	'ell				
Surface Ow	ner Burea	u of Land M	fanagemen	t Mineral (	Owner	Bureau of L	and Managemer	nt	Lease 1	No. NM54	865	
30-015						N OF RE						
Unit Letter	Section	Township	Range	Feet from the		h/South Line	Feet from the	East/We	st Line	County		
ī	35	198	29E 2610			South 430 East				Eddy		
	<u> </u>	<u> </u>	Lati	tude	I	Longitud	e	!	•			
					URE	OF RELI						
Type of Rele	ase Oi	1 / Prod. Wtr.			Volume of	5 bbl Fluid						
Source of Re	lease Inj. I	ine valve			Date and Hour of Occurrence Date and Hour of Disco							
						5/30/08 8:10 AM 5/30/08 8:10 AI					<u>M</u>	
Was Immediate Notice Given?  X Yes □ No □ Not Require						If YES, To Whom?  Jim Amos w/ BLM & Mike Bratcher w/NMOCD						
By Whom? Bill Hearn						Date and H	our 5/30/08	10:01A	И			
Was a Watercourse Reached?  Yes X No						If YES, Volume Impacting the Watercourse.						
If a Watercou			L. T11. *					<del></del>				
	ked vehicle	over live inje	ction line va				s off fiberglass in	jection lin	e.			
cleanup remed	AREA: 186 CTION: Pic liation action	' X 70' cked up standi n.	ing fluid w/	vacuum truck. I			_				M/OCD for further	
regulations all public health o should their op	operators and the environ erations have needed as	re required to nment. The a ve failed to ad lition, NMOC	report and/occeptance of equately involutely	or file certain rel of a C-141 report vestigate and rer	ease not t by the nediate	otifications and NMOCD mar contamination	nowledge and und perform correcting ked as "Final Report that pose a threat the operator of res	ve actions port" does at to groun	for releat not relie d water,	ases which move the operate surface water	nay endanger tor of liability er, human health	
4	Very.	1/	, , , ,	[ ]			OIL CONS		• /			
Signature: 1001MW ASULIALISTEN						Annroyed by D	istrict Supervisor	Gum		Final C-141 sub	tions to be completed <u>and</u> mitted with confirmation on or before to	
Printed Name:	Donna Hu	ddleston					Istrict Supervisor	<u> </u>	3	Expiration Date		
Title: Producti	ion Tech				_   _	Approval Date:	7-3-08 INEATION REQU	Expi	ration D	ate: 9-23	,-08	
E-mail Address	: dhuddlest	on@stmaryla	nd.com		c	onditions cont	amination reaches back site specific acceptable	ground levels	. ]	A44. 1 1 f	_	
	5/02/2008			8-1789		or a warr	anted, a work plan may or before <b>8-20-</b> 4	be required.	alation of	Attached 1	P-180	
Date: 06/02/2008 Phone: 432-688-1789 ttach Additional Sheets If Necessary						remediation work	plan based on delinea itted for approval to the	tion should b		1	48 hours prior to nples where analyse	

summarizing all actions taken and/or to be taken to mitigate

The plan must include general site characteristics, site ranking score, soil remediation action levels, soil remediation methods, and planned analytical testing for TPH, B-TEX, Chlorides or any

other COCs as applicable. Please use the "Guidelines for Remediation of Leaks, Spills, & Releases" as your guide. This document may be found at the following link: http://www.emnrd\_state\_nm\_us/ocd/documents/7C\_spill1\_pdf

environmental damage

St. 19

are to be presented to OCD