

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form
JUL 17 2008
OCD-ARTESIA

Release Notification and Corrective Action

SEB0820033727
NSEB0820033340

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company ExxonMobil	7673	Contact Toni Collier
Address P.O. Box 4358, Houston, TX 77210		Telephone No. 281-654-1133
Facility Name Avalon Delaware Unit	30-015-24524	Facility Type Flowline

Surface Owner BLM	Mineral Owner BLM	Lease No. NMNM 0119
-------------------	-------------------	---------------------

LOCATION OF RELEASE

Unit Letter C	Section 30	Township 28E	Range 20S	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude N32.32.5.22 Longitude 104.13.18.92

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 56 bbls	Volume Recovered 0 bbls
Source of Release 2 7/8" flowline	Date and Hour of Occurrence 5/26/08	Date and Hour of Discovery 5/26/08 8:30AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bractcher	
By Whom? Shelby Pennington	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
2 7/8" flowline, 4 years old leaked due to internal corrosion. Line was isolated.

Describe Area Affected and Cleanup Action Taken.*
Contaminated soil was immediately excavated. Delineation plan is being worked to submit to NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Kevin M. Dillow</i>		OIL CONSERVATION DIVISION	
Printed Name: Kevin M. Dillow		Approved by District Supervisor: <i>TCumby SB</i>	
Title: Compliance Supervisor		Approval Date: 7-18-08	Expiration Date:
E-mail Address: Kevin.M.Dillow@exxonmobil.com		Conditions of Approval:	
Date: 6/4/08	Phone: 281-654-1557	Attached <input checked="" type="checkbox"/> 2RP-201	

* Attach Additional Sheets If Necessary

SEB0820033824

New Mexico Energy, Minerals and Natural Resources Department

Bill Richardson
Governor

Joanna Prukop
Cabinet Secretary
Reese Fullerton
Deputy Cabinet Secretary

Mark Fesmire
Division Director
Oil Conservation Division



CERTIFIED MAIL—Return Receipt Requested
7007 2680 0001 6451 2704

July 18, 2008

ExxonMobil
Attn: Kevin M. Dillow
PO Box 4358
Houston, TX 77210

RE: Avalon Delaware Unit Lease: NM-01119 (30-015-24524)
Latitude: 32.534783; Longitude: 104.221922
2RP-201

Dear Sir:

This office is in receipt of your C-141 regarding the produced water release at this facility.

NMOCD Rule 19.15.3.116 states in part, "...The responsible person must complete **division approved corrective action** for releases which endanger public health or the environment. Releases will be addressed in accordance with a **remediation plan** submitted to and approved by the division or with an abatement plan submitted in accordance with Section 19 of 19.15.1 NMAC."

Information and tools for proper corrective action may be found in the Environmental Handbook on our web site at the following link:

http://www.emnrd.state.nm.us/oed/documents/7C_spill1.pdf

The following actions are **required** to be addressed in the **remediation plan**:

- Determine the horizontal and vertical delineation of the spill by sampling.
- Prepare a sketch of the site indicating where and at what depths the samples were taken.
- Submit laboratory results of sampling as well as the proposed remediation with the plan.

Remediation requirements may be subject to other federal, state, and local laws or regulations.

Within 30 days, **on or before August 20, 2008**, completion of a remediation work plan should be finalized and submitted to the Division summarizing all actions taken or to be taken to mitigate environmental damage related to the leak, spill or release for approval.

Please be advised that NMOCD acceptance and/or approval of documents or work plans does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance and/or approval of documents or work plans do not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

If I may be of further assistance with this matter or should you have any questions, please feel free to contact me.

Sincerely,

Sherry Bonham
NMOCD District II, Artesia
(505) 748-1283 ext 109
E-mail: sherry.bonham@state.nm.us

