

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

Oil Cons.  
N.M. DIV-Dist. 2

1301 W. Grand Avenue  
Artesia, NM 88210

Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT - " for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> WIW		5. LEASE DESIGNATION AND SERIAL NO. LC-029419-A	
2. NAME OF OPERATOR The Wiser Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P.O. Box 2568 Hobbs, New Mexico 88241		7. UNIT AGREEMENT NAME Skelly Unit	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface  660' FNL & 1880' FEL Unit B		8. WELL NAME AND NO. 42	
		9. API WELL NO. 30-015-05356	
		10. FIELD AND POOL, OR WILDCAT Grayburg Jackson 7-Rivers-QN-GB-SA	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 22-T17S-R31E	
14. PERMIT NO	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3875' DF	12. COUNTY OR PARISH Eddy County	13. STATE NM

16. Check Appropriate Box to indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT * <input type="checkbox"/>
(Other) <input type="checkbox"/>	
(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured an true vertical depths for all markers and zones pertinent to this work.)

7/30/03 MIRU Mayo Marrs Casing Pulling Inc. NU BOP. RIH w/2-3/8" tbg. Tag CIBP @ 2100'. CIBP set 10/03/01. Accepted by Don Early w/BLM. Circulate hole with 10# mud. Spot 20 sks. f/2100'-1811'.  
7/31/03 No tag required. Spot 25 sks. f/1600'-1320'. POH & WOC. Tag @ 1320'. Witnessed by Don Early w/BLM. Perforate @ 620'. Set pkr. @ 186'. Squeeze 130 sks.  
8/01/03 Tag @ 343'. ND BOP. Cut off WH & anchors. Spot 15 sks. f/60' to surface. Install dry hole marker. Level pit & cellar. RDMO. Well is P & A.

Approved as to plugging of the well bore.  
Liability under bond is retained until  
surface restoration is completed.

18. I hereby certify that the foregoing is true and correct.

SIGNED Mary Jo Turner TITLE Production Tech II DATE October 22, 2003

(This space for Federal or State office use)

APPROVED BY (ORIG. SGD.) ALEXIS C. SWOBODA TITLE PETROLEUM ENGINEER DATE NOV 04 2003  
CONDITIONS OF APPROVAL, IF ANY:

Accepted for Records  
See Instruction On Reverse Side