Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SEP 19 2008

FORM APPROVED OMB NO 1004-0135 Expires. July 31, 2010

SUNDRY N	OTICES AND F	REPORTS ON	I WELLS
----------	--------------	------------	---------

Do not use this form for proposals to drill or to re-enter an

3. Lease Serial No NMLC029420A

abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tr	be Name	
SUBMIT IN TRIPLICATE - Other instructions on rev			de.		7. If Unit or CA/Agreement, Name and/or No NMNM71030A		
1 Type of Well ☐ Oil Well ☐ Gas Well ☑ Other INJECTION					8 Well Name and No SKELLY UNIT 26		
2. Name of Operator Contact CINDY BUS FOREST OIL CORPORATION E-Mail. CABush@forestoil.com					9. API Well No 30-015-05157-00-S1		
3a. Address 3b Phone No. 707 17TH STREET SUITE 3600 Ph: 303-8 DENVER, CO 80202					10 Field and Pool, or Exploratory GRAYBURG		
4 Location of Well (Footage, Sec., T., R., M., or Survey Description)					11 County or Parish, and	State	
Sec 15 T17S R31E NWSE 1880FSL 1980FEL				:	EDDY COUNTY, N	М	
12. CHECK APPE	ROPRIATE BOX(ES) TO IN	IDICATE NATU	RE OF NO	OTICE, RI	EPORT, OR OTHER D	ATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
Notice of Intent	□ Acidize	□ Deepen		□ Product	_	Water Shut-Off	
-	☐ Alter Casing	□ Fracture Tre	at	□ Reclama	ation	Well Integrity	
Subsequent Report	☐ Casing Repair	□ New Constru	uction	□ Recomp	lete	Other	
☐ Final Abandonment Notice	Change Plans	☐ Plug and Ab	andon	☐ Tempor	arily Abandon		
	☐ Convert to Injection	Plug Back		□ Water D	Disposal		
following completion of the involved testing has been completed. Final Al determined that the site is ready for f MIT test and return to Active I 8-18-08 - Spot rig. Hobbs and didn't work on BOP. Couldn't I flowing to flow line. 8-19-08 - DN WH & take rubb tbg tester, Test 101 jts BIH w/ Tbg tester, RU pump truck, pr 8-20-08 - RU pmp truck, DN c 500 psi for 30 min, held good, Chart attached	pandonment Notices shall be filed or inal inspection.) njection chors replace 3 anchors, RU out BOP waited on mechanic er of NU screw on flange unspkr 5 1/2 AD 1 pkr. Replace 2 ess to 500 psi held good for eatch pan & shut in BOP circ in RD PU.	PU, bleed well to to fix hydrolic pn set pkr & NU BOF 2 jts 2 3/8 tbg ipc 30 minutes, unse	o frac tank, np on catcl P, start PO , set pkr @ et pkr.	catch pan n pan, let t H tbg and 3186 RD 3186' pres	n, have been completed, and bg pkr RU	the operator has	
14. Thereby certify that the foregoing is	true and correct. Electronic Submission #629 For FOREST OIL 0 mitted to AFMSS for processi	47 verified by the CORPORATION, s	BLM Well I sent to the 0	nformation Carlsbad /11/2008/6	ySGAYE,"Deputy Field Ins	pector ESIA	
Name (Printed/Typed) CINDY BUSH			REGULA	TORY TEC	CHNICIAN		
Signature (Electronic Submission)			09/11/200				
	THIS SPACE FOR	FEDERAL OR	STATE O	FFICE US	SE.		
Approved By ACCEPTED			DUNCAN WHITLOCK LeLEAD PETROLEUM ENGINEERING TECH Date 0		Date 09/16/20		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon			Carlsbad				
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a crin statements or representations as to a	ne for any person kno ny matter within its j	owingly and vurisdiction.	villfully to m	ake to any department or age	ncy of the United	

