

January 22, 2008

Oil Conservation Division 1301 W. Grande Ave. Artesia, N.M. 88210

Attention: Bryan Arrant

RE:

Burch Keely Unit #989	Unit H, Sec 13, T17S - R29E	Eddy County
Burch Keely Unit #991	Unit F, Sec 18, T17S - R30E	Eddy County
Burch Keely Unit #992	Unit G, Sec 18, T17S - R30E	Eddy County
Burch Keely Unit #993	Unit P, Sec 18, T17S - R30E	Eddy County
Burch Keely Unit #994	Unit P, Sec 24, T17S - R29E	Eddy County C 2(179
Burch Keely Unit #995	Unit N, Sec 23, T17S - R29E	Eddy County 30 015 36179
Burch Keelv Unit #996	Unit E. Sec 23, T17S - R29E	Eddy County

Dear Bryan:

Marbob Energy has conducted a review to determine if an H2S contingency plan is required for the above referenced well. We were able to conclude that any potential hazardous volume would be minimal. H2S concentrations of wells in this area from surface to TD are low enough; therefore we do not believe that an H2S Contingency Plan would be necessary.

Please advise us if you feel differently or need further information.

Sincerely,

Nancy Agnew Land Department

1 January Concer

/na