

District I -  
1625 N French Dr , Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

OCT 20 2008  
OCD-ARTESIA  
Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

30-015-26134

**OPERATOR**

☐ Initial Report ☐ Final Report

Name of Company SANDLOTT ENERGY	Contact JACKIE BREWER
Address P.O BOX 711 LOVINGTON NM 88260	Telephone No. 575-631-4592
Facility Name RESLER YATES # 381	Facility Type ACTIVE PRODUCTION WELLHEAD

Surface Owner NMSLO	Mineral Owner	Lease No.30-015-26134
---------------------	---------------	-----------------------

**LOCATION OF RELEASE**

Unit Letter G	Section 32	Township 18S	Range 28E	Feet from the 1884	North/South Line NORTH	Feet from the 1394	East/West Line EAST	County EDDY
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release HISTORICAL	Volume of Release N/A	Volume Recovered N/A
Source of Release ACCUMULATED RELEASE FROM ACTIVE WH	Date and Hour of Occurrence	Date and Hour of Discovery
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

NOT APPLICABLE


Describe Cause of Problem and Remedial Action Taken.\*

LEAK AROUND UNUSED TANKS WELLHEAD STUFFING LEAK LESS THAN 5 BBLs

Describe Area Affected and Cleanup Action Taken.\*

DUG AROUND WELLHEAD 3FT BY 6FT RADIUS APPROX. 3FT IN DEPTH HAULED SOIL TO CRI REFILLED WITH CLEAN SOIL  
REMOVED OLD TANKS , DUG REMOVED AND HAULED SOIL TO CRI

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>		
Printed Name: JACKIE BREWER	Approved by District Supervisor:		
Title: OPERATOR	Approval Date:	Expiration Date:	
E-mail Address: brewer212@aol.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 10-14 2008	Phone: 575-631-4592		

\* Attach Additional Sheets If Necessary

Accepted for record  
NMOCD



OCT 22 2008