

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd, Aztec, NM 87410
District IV
1220 S. St. Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

MAR 02 2009

Form C-103
June 19, 2008

WELL API NO. 30-015-34644
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Livingston Ridge 36 State
8. Well Number 1
9. OGRID Number 20165
10. Pool name or Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other	
2. Name of Operator Samson Resources	
3. Address of Operator 200 N Loraine St, Ste 1010, Midland, TX 79701	
4. Well Location Unit Letter <u>O</u> : <u>660</u> feet from the <u>South</u> line and <u>1980</u> feet from the <u>East</u> line Section <u>36</u> Township <u>22S</u> Range <u>31E</u> NMPM Eddy County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3471' GR	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER:
Recomplete to Morrow; Dually complete w/Atoka
☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1/19/09:
MIRU PU. ND tree. NU BOP.
POH w/ pkr.
Retrieve RBP w/ 14297.
Run completion assembly.
Open sleeve. Swab test Atoka.
Close sleeve. Press test tbq to 920 psi.
No communication between Morrow & Atoka.
Unable to pump off pump out plug.
Press test tbq to 5000. No communication.
Cut and perf tailpipe.
2/4/09:
Flow test Morrow up tbq.
10/64 ck 93 BW 0 BO 580 mcf w/ FTP 1050 psi.
Atoka Shut in.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kenny Krawietz TITLE District Engineer DATE 02/25/2009

Type or print name Kenny Krawietz E-mail address: kkrawietz@samson.com PHONE: 432-683-7063

For State Use Only

APPROVED BY: _____ TITLE _____ DATE _____

Conditions of Approval (if any):