					UU 0 0 0000	
	Submit 3 Copies To Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources		JUL 3 0 2009	Form C-103	
	<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	May 27, 2004	
	District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505			30-015-201	
	District III				5. Indicate Type of Lease STATE	FEE 🗌
	District IV				6. State Oil & Gas Lease No.	
	1220 S. St. Francis Dr., Santa Fe, NM 87505					
ļ	SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit A	greement Name	
	DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				North Square	Lake Unit
- {	1. Type of Well: Oil Well] Gas Well □ Other Water Injection			8. Well Number 4	
	2. Name of Operator CBS Operating C	me of Operator CBS Operating Corp.			9. OGRID Number 216852	
	. Address of Operator				10. Pool name or Wildca	t
	P O Box 2236 Midland TX 79702			Square Lake	GB SA	
	4. Well Location Unit Letter I : 1650 feet from the South line and 990 feet from the east line section 19 Township 16S Range 31E NMPM Eddy County NM 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3872 GR					
	t type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water					
ı	Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction Material					
	12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
	NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING [
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB						A 🗆
	POLL OR ALTER CASING	MULTIPLE COMPL	لسا	CASING/CEMEN	JOB []	
-	OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.					
	MI&RU 7-24-09 - Unset packer. Test tubing, found two bad joints.					
	Replaced tubing, and ran back in hole. Circulated packer fluid and set packer.					
	Notified NMOCD to witness new MIT. Tested backside to 350# for 30 minutes, held okay. Delivered original chart to NMOCD, copy attached.					
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines [], a general permit [] or an (attached) alternative OCD-approved plan [].						
1	SIGNATURE 6 - A .	dujo 3	_TITLE	Engineer		7-29-2009
	Type or print name M. A. S. For State Use Only	irgo, III	E-mail ad	dress: mastre:	432 @aol.comTelephone	2/685-0878 :No.
	\mathcal{D}) INGE		COMPLIANCE	ACCUSA	7/21/08
	APPROVED BY:Conditions of Approval (if any):	/ INUS	_TITLE_C	OMPLIANCE	DEFLECT DATE	11>409

