## RECEIVED

FEB 1 7 2010

Submit One Copy To Appropriate District State of New Mexico Form C-103 Office NMOCD ARTESIA March 18, 2009 Energy, Minerals and Natural Resources District I WELL API NO. 1625 N French Dr , Hobbs, NM 88240 30-005-00158 District II OIL CONSERVATION DIVISION 1301 W. Grand Ave, Artesia, NM 88210 5. Indicate Type of Lease 1220 South St. Francis Dr. District III STATE FEE X 1000 Rio Brazos Rd, Aztec, NM 87410 Santa Fe, NM 87505 6. State Oil & Gas Lease No. District IV 1220 S St Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A Ruby Jo ATY DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 8. Well Number #1 1. Type of Well: Oil Well Gas Well X Other PA 2. Name of Operator 9. OGRID Number Yates Petroleum Corporation 025575 3. Address of Operator 10. Pool name or Wildcat 105 S. 4th Street, Artesia, NM 88210 Wildcat San Andres 4. Well Location Unit Letter O: 660 feet from the South line and 1980 feet from the East line Section 14 Township 8S Range 26E NMPM Chaves 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING CHANGE PLANS TEMPORARILY ABANDON COMMENCE DRILLING OPNS. P AND A MULTIPLE COMPL PULL OR ALTER CASING CASING/CEMENT JOB □ Location is ready for OCD inspection after P&A All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4" above ground level has been set in concrete. It shows the OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. Poured onsite concrete bases do not have to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from nonand the second of the second of the second retrieved flow lines and pipelines. When all work has been completed, return this form to the appropriate District office to schedule an inspection. **SIGNATURE** TITLE TYPE OR PRINT NAME - Las E-MAIL:

For State Use Only

APPROVED BY:

Conditions of Apploval (if any):