RECEIVED

AUG 2 5 2010

03 <u>)07</u>

Submit 2 Copies To Appropriate District	State of New M	exico 2 3 2010	İ	Form C-103
Office District I	Energy, Minerals and NHOCD ARTESIA		October 25, 2007	
1625 N. French Dr., Hobbs, NM 88240	1414	OOD ATTICOIA	WELL API NO	~ 1
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION	V DIVISION	30-015	- <u>23321</u>
District III	1220 South St. Francis Dr.		5. Indicate Type of	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 8	1	STATE STATE	
District IV	Santa re, min o	17505	6. State Oil & Ga	s Lease No.
1220 S St. Francis Dr., Santa Fe, NM 87505			L-2	764
	AND REPORTS ON WELL	S		Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS	TO DRILL OR TO DEEPEN OR PI	LUG BACK TO A		Ü
DIFFERENT RESERVOIR USE "APPLICATION	ON FOR PERMIT" (FORM C-101) F	OR SUCH	Irish Hills	KW St. Com
PROPOSALS.) 1. Type of Well. Oil Well Gas Well Q Other PA			8 Well Number 2	
	WCII KI OHICI PA		9. OGRID Numbe	
2. Name of Operator				SI .
Yates Petroleum Corporation			025575 10. Pool name or	Wildow
3. Address of Operator			_	
105 S. 4th Street, Artesia, NM 88210			Yenasco Dra	w Permo Pena
4. Well Location	: ·		_	
Unit Letter 6: 1980 f			line	
Section 2 Township	195 Range 24E NMPN	A Eddy County		
11.	Elevation (Show whether DR	R, RKB, RT, GR, etc.)		
12. Check Appropriate Box to Inc	licate Nature of Notice, I	Report or Other Da	ata	
12. Oxford appropriate	,	·		
NOTICE OF INTER	NTION TO:	SUBS	EQUENT REF	PORT OF:
PERFORM REMEDIAL WORK 🔲 PLUG AND ABANDON 🔲 📗 REMEDIAL WORK				ALTERING CASING \Box^{-1}
TEMPORARILY ABANDON CH	IANGE PLANS	COMMENCE DRIL	LING OPNS.	P AND A
	ILTIPLE COMPL	CASING/CEMENT	JOB 🗌	
OTHER:				
All pits have been remediated in con				
Rat hole and cellar have been filled a				
A steel marker at least 4" in diameter	and at least 4' above ground:	level has been set in	concrete. It shows	the
OPERATOR NAME, LEASE				
UNIT LETTER, SECTION, T			N HAS BEEN WE	LDED OR
PERMANENTLY STAMPED	ON THE MARKER'S SUR	FACE.		
The location has been leveled as near	dy as possible to existing see	and contour and has be	an aloomed of all in	
other production equipment.	ly as possible to original grou	ind contour and has be	sen cleared of an ju	mik. trasii. now fines and
Anchors, dead men, tie downs and ris	sers have been out off at least	two feet below ground	d level	
If this is a one-well lease or last rema				ed in compliance with
OCD rules and the terms of the Operator's				
from lease and well location.	, by berries man erooms brown		errow editalizations can	a jax 111, 0 00011 101110 104
All metal bolts and other materials har	ve been removed. Portable ba	ases have been remove	ed. (Poured ousite of	concrete bases do not have
to be removed.)			(
All other environmental concerns har	ve been addressed as per OCI	O rules.		
Pipelines and flow lines have been at			MAC. All fluids h	nave been removed from
non-retrieved flow lines and pipelines.		,,,,,,		
* *				
When all work has been completed, return				
inspection has to be made to a P&A locati				
inspection has to be made to a P&A location.	on because it does not meet the		nalty may be assess	sed.
SIGNATURE Jony Marke			nalty may be assess	
SIGNATURE Jonny Marshe	on because it does not meet it		nalty may be assess	oate <u>8-24/0</u>
	on because it does not meet the		nalty may be assess	sed.

יצם משונטממתי