


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

Name of Company		COG OPERATING LLC 229137		Contact		Pat Ellis	
Address		550 W. Texas, Suite 100, Midland, TX 79701		Telephone No.		432-230-0077	
Facility Name		RJU INJECTION TRUNK-LINE		Facility Type		Trunk-Line	
Surface Owner		Federal		Mineral Owner		Lease No. (API#) 30-015-03765	

LOCATION OF RELEASE							
Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line
A	34	17S	29E	660	NORTH	654	EAST
							County EDDY

Latitude 32 47.702 Longitude 104 03.251

NATURE OF RELEASE	
Type of Release	Produced Water
Source of Release	2" Water flood Trunk Line
Volume of Release	190bbls
Volume Recovered	130bbls
Date and Hour of Occurrence	04/15/2010
Date and Hour of Discovery	04/15/2010 12:00p.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required
If YES, To Whom?	Mike Bratcher-OCD Terry Gregston-BLM
By Whom?	Josh Russo
Date and Hour	04/15/2010 9:01 p.m.
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*	
Describe Cause of Problem and Remedial Action Taken.*	
The leak was caused by a new installation of faulty fiber/poly trunk line. The entire line is being removed and completely replaced.	
Describe Area Affected and Cleanup Action Taken.*	
190bbls of produced water was initially released and covered an area of 75'x100' next to the line in the pasture. A vacuum truck was immediately called and recovered 130bbls of fluid. One-call protocol will be made and a sundry will be submitted for archeological /wildlife sensitivity clearance prior to soil sampling by Tetra Tech. (The spill site area is located 150 yards west of the following: COG OPERATING LLC, RJU UNIT #124, 660FNL 654 FEL, Sec. 34-T17S-R29E, Eddy Co. NM, API#30-015-03765)	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Signature:	
Printed Name:	Josh Russo
Title:	HSE Coordinator
E-mail Address:	jrusso@conchoresources.com
Date:	04/20/2010
Phone:	432-212-2399
OIL CONSERVATION DIVISION	
Approved by District Supervisor:	
Approval Date:	OCT 22 2010
Expiration Date:	
Conditions of Approval:	Remediation per OCS Rules
Attached	<input type="checkbox"/>
Approved Remediation Plan in effect	

* Attach Additional Sheets If Necessary

PMLB 1029554780

2RP-449