

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-26891

Release Notification and Corrective Action

17, MCB 0930940125

147179

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	CHESAPEAKE OPERATING, INC.	Contact	BRADLEY BLEVINS
Address	P. O. BOX 190 HOBBS, NM 88241	Telephone No.	575-391-1462
Facility Name	BCR Fed. #1	Facility Type	Oil Well

Surface Owner	Mineral Owner	Lease No.
---------------	---------------	-----------

LOCATION OF RELEASE API #30-015-31376

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	3	23S	28E	640	NORTH	330	EAST	EDDY

Latitude 32.34632 Longitude 104.06715

NATURE OF RELEASE API 30-015-26891

Type of Release	Produced water	Volume of Release	30 BBLS	Volume Recovered	10 BBLS
Source of Release	Flow line ruptured	Date and Hour of Occurrence	10/29/09 7:00 A.M.	Date and Hour of Discovery	10/29/09 90:00 A.M.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher		
By Whom?	Cliff Brunson-BBC International, Inc.	Date and Hour	10/29/09 12:10 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A plastic flow line ruptured releasing produced water. Vacuum trucks were used to recover free fluid.

Describe Area Affected and Cleanup Action Taken.*

10 BBLS of fluid was recovered. A remediation plan was submitted to and approved by M. Bratcher of the NMOCD. Soil removal was conducted and disposed of at an NMOCD-approved disposal facility. The site was backfilled and closed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: BRADLEY BLEVINS	Approved by District Supervisor 		
Title: EHS Specialist	Approval Date: 2/15/2001	Expiration Date: N/A	
E-mail Address: bradley.blevins@chk.com	Conditions of Approval: NW Final		Attached <input type="checkbox"/>
Date: 6/16/10	Phone: 575-391-1462		

* Attach Additional Sheets If Necessary

2 RP. 362