

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-36560

Release Notification and Corrective Action

7 KMW 1105-94469

OPERATOR



☒ Initial Report ☐ Final Report

Name of Company Devon Energy	6137	Contact <input type="checkbox"/> Ernie Duran
Address P. O. Box 250 Artesia, NM 88211		Telephone No. <input type="checkbox"/> 575-513-1768
Facility Name Cowpens 28 Fed #1		Facility Type <input type="checkbox"/> Gas Well
Surface Owner	Mineral Owner	Lease No. <input type="checkbox"/>

LOCATION OF RELEASE

Unit Letter J	Section 28	Township 19S	Range 31E	Feet from the 1650	North/South Line South	Feet from the 1650	East/West Line East	County Eddy County, NM
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	---------------------------

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 140 BPW	Volume Recovered <input type="checkbox"/> 140 BPW
Source of Release Drain Line Connection	Date and Hour of Occurrence 2-9-11 8:00 AM	Date and Hour of Discovery 2-9-11 8:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Left msg BLM Jim Amos	
By Whom? <input type="checkbox"/> Ernie Duran	Date and Hour <input type="checkbox"/> 2-10-11 10:30 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Drain line connection on the fiberglass water tank had frozen overnight and parted (pulled) away from the tank causing a 140 bbls spill.		
Describe Area Affected and Cleanup Action Taken.* The entire 140 bbl produced water spill was contained within the lined containment. All 140 bbls of produced water was recovered causing to environmental impact outside of the lined containment. Called vacuum truck to pick up water.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Ernie Duran	Signed By  Approved by <input type="checkbox"/> District Supervisor	
Title: Asst. Production Foreman	Approval Date: 3/3/11	Expiration Date:
Date: 2-11-11 Phone: (575) 513-1768	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:**

4/3/11

RECEIVED
FEB 23 2011
NMOCD-ARTESIA

2 RP-615