

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 V. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 TH Street		Telephone No. 575-748-1471
Facility Name Monsanto Foster SWD #1	API Number 30-015-10340	Facility Type SWD

Surface Owner Federal	Mineral Owner Federal	Lease No.
--------------------------	--------------------------	-----------

LOCATION OF RELEASE

Unit Letter D	Section 5	Township 20S	Range 25E	Feet from the 660	North/South Line North	Feet from the 660	East/West Line West	County Eddy
------------------	--------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------



Latitude 32.60791 Longitude 104.51304

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 6 B/PW	Volume Recovered 5 B/PW
Source of Release Charge Pump	Date and Hour of Occurrence 9/1/2009 - AM	Date and Hour of Discovery 9/1/2009 - AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Mechanical seal on charge pump broke. Vacuum truck called. Shut off all pipelines leading to the charge pump.		
Describe Area Affected and Cleanup Action Taken.* Approximate area: 50' X 15' (contained within pump house, cement barrier around base of building). Vacuum truck picked up remaining produced water. Called service company for immediate repairs of charge pump and put back in service. Depth to Ground Water: >100' (approximately 200'), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0. Based on amounts released/recovered and contained within the pump house, Yates Petroleum Corporation requests closure.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by District Supervisor: 	
Printed Name: Robert Asher	Approval Date: 3/24/2011	Expiration Date: N/A
Title: Environmental Regulatory Agent	Conditions of Approval: N/A	Attached <input type="checkbox"/>
E-mail Address: boba@yatespetroleum.com	2RP-	
Date: Wednesday, September 09, 2009	Phone: 575-748-4217	

* Attach Additional Sheets If Necessary

2RP-658

LAZ ENTRY