<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240

District II

1801 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Road, Aztec, NM 87410

District IV

* Attach Additional Sheets If Necessary

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

> Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

JUN - 4 2009 Form C-141 Revised October 10, 2003

> Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

> > 2RP 663

| 0-015-2 | 8281 | | | ease Notifi | catio | on and Co | orrective A | ction | 1 | | | | |
|---|--|---|---|---|----------------------------------|--|---|--|---|--|---|---------------------------------------|--|
| 1Kmi 1108 344978 | | | | | | OPERA | | | | | | | |
| Name of Company OXY USA | | | | | | Contact Kelton Beaird | | | | | | | |
| Address 102 S Main Carlsbad, NM 88220 | | | | | | Telephone No. (O) 575-628-4121 C) 575-390-1903 | | | | | | | |
| Facility Name Neff Fed. # 3 | | | | | | Facility Type SWD | | | | | | | |
| Surface Owner BLM Mineral Owner | | | | | | Lease No. | | | | | | | |
| | | | | LOCA | ATIO | N OF REI | LEASE | | | | | | |
| Unit Letter | Section | Range | Feet from the | | h/South Line | Feet from the | East/\ | West Line | County | | | | |
| \triangle | 25 | 22S | 31E | | | | | | | Eddy | | | |
| | | · · · · · · · · · · · · · · · · · · · | La | titude | • | Longitud | le | | | | · · · · · | | |
| | | | | | | g E OF RELI | | | | | ٠. | | |
| Type of Rele | ase Produc | ed Water | | NAI | UKI | | Release +50bbls | | Volume I | Recovered | 30bbls | 2 | |
| Type of Release Produced Water Source of Release Steel Flowline | | | | | | Date and Hour of Occurrence | | | Date and Hour of Discovery | | | | |
| | | | | | | 5-30-09 @ 10:45am | | | | | | | |
| Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required | | | | | | If YES, To Whom? Mike Bratcher-NMOCD (left message), Jim Amos-BLM | | | | | | | |
| By Whom? Kelton Beaird –HES Oxy | | | | | | Date and Hour See above | | | | | | | |
| Was a Watercourse Reached? | | | | | | If YES, Volume Impacting the Watercourse. | | | | | | | |
| ☐ Yes ☒ No | | | | | | | | | | | | | |
| | | em and Remed | | | | | | | | | | | |
| | was across | the location a | ınd down | en.* the road, Approx I for approval. | 135' lo | ng by 24' wide | e. A vac-truck wa | as called | I to pick up | remaining | fluid. | Delineation | |
| regulations al public health should their o | operators a or the environment of the environment on the environs had been to be a controlled to the environment. In accordance of the environment | are required to onment. The ave failed to a ddition, NMO | report an acceptanc dequately CD accept | is true and comp d/or file certain re e of a C-141 repo investigate and re tance of a C-141 r | elease r ort by the emedia | notifications an ne NMOCD ma te contamination | d perform correctorked as "Final Room that pose a three the operator of records." | tive acti eport" deat to greesponsi | ons for rele oes not reli ound water bility for co | eases which eve the oper , surface wa ompliance w | may e rator o iter, hu vith an | ndanger f liability ıman health | |
| Signature: | | | | | | Approved by Disigned Brying Brancon | | | | | | | |
| Printed Name | | aira | | | | | | | | | | . | |
| Title: HES S | ecialist | | | · · · · · · · · · · · · · · · · · · · | | Approval Date | 3/29/zcx1 | | Expiration I | Date: | | | |
| E-mail Addres | ss: kelton l | oeaird@oxy.co | om | - | | Conditions of | Approval: La Mic | edraha | i per | Attached | | | |
| Date: 6-1-09 | | | | | | UNICA CO | Conditions of Approval Remediation for | | | | | | |