

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-28281

Release Notification and Corrective Action

OPERATOR

Initial Report XX Final Report

Name of Company	Oxy USA WTP	Contact	Dusty Wilson
Address	1017 W. Stanolind Rd	Telephone No.	(575) 397-8247
Facility Name	Neff Federal # 3	Facility Type	SWD

Surface Owner	BLM	Mineral Owner		Lease No.	
---------------	-----	---------------	--	-----------	--

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	25	22S	31E					Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Produce Water	Volume of Release	50 bbls	Volume Recovered	30 bbls
Source of Release	Steel Flowline	Date and Hour of Occurrence	05/30/2009	Date and Hour of Discovery	05/30/2009
Was Immediate Notice Given?	X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher		
By Whom?	Kelton Beard	Date and Hour	05/30/2009		
Was a Watercourse Reached?	<input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.	n/a		
If a Watercourse was Impacted, Describe Fully.*	N/A				


Describe Cause of Problem and Remedial Action Taken.*

Pop off valve and 2" steel line corroded and separated causing leak. Vac truck was dispatched and picked up all free standing fluids. Soil Samples were obtained and analyzed. A work plan to excavate 3' at the spill area, set and compact a clay liner in the bottom of the excavated area, and backfill with clean like soils was agreed upon by NMOCD Representative, Mike Bratcher. This work plan was carried out according to the agreement and the site is closed.
A Composite Sample was taken to test for TPH+BTEX as agreed. Results showed to be acceptable levels according to NMOCD.

Describe Area Affected and Cleanup Action Taken.*

Remediated to NMOCD Requirements.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Dusty L. Wilson		Approved by District Supervisor: Accepted for record NMOCD	
Title: HES Specialist		Approval Date:	Expiration Date:
E-mail Address: dusty_wilson@oxy.com		Conditions of Approval: <i>Analytical data to be submitted to OED</i>	
Date: 10/20/2009	Phone: (575) 397-8210	Attached <input type="checkbox"/>	

- Attach Additional Sheets If Necessary

2RP-603