

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

RECEIVED APR 29 2010

30-015-05123

Release Notification and Corrective Action

7 KMW 1107650803

OPERATOR

☒ Initial Report

☐ Final Report

Name of Company	SandRidge Energy	270265	Contact	Ron Ragland
Address	3504 NW County Road Hobbs, N.M.		Telephone No.	(575) 392-9797
Facility Name	State A&B Battery		Facility Type	Battery

Surface Owner	State	Mineral Owner	Lease No.	B-2613 & B-3014
---------------	-------	---------------	-----------	-----------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	16	17S	31E	1650'	South	660'	East	Eddy

Latitude 32.83182 Longitude -103.86765

NATURE OF RELEASE

Type of Release	Oil & Water	Volume of Release	50 bbls.	Volume Recovered	35 bbls.
Source of Release	Flowline	Date and Hour of Occurrence	4/28/2010 6:00 a.m.	Date and Hour of Discovery	4/28/2010 9:30 a.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Randy NMOCD - Artesia Office		
By Whom?	Roy Munoz	Date and Hour	4/28/2010 2:45 p.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
N/A					
Describe Cause of Problem and Remedial Action Taken.*					
3" X 2' flowline had a hole in nipple Replaced nipple and called vac. truck					
Describe Area Affected and Cleanup Action Taken.*					
Inside dike - (20' x 24') & continued 2400' down a ravine. (The 1 st 1000' was 6" wide. The rest was 1400' X 2' wide). Affected area was all dirt. Cleaned area with vac. truck recovering 11 bbls. from dike and 24 bbls. from ravine.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

OIL CONSERVATION DIVISION

Signature: Ron Ragland	By Mary Jo Turner	Approved by District Supervisor	Signed By: Mike Brannon
Printed Name: Ron Ragland		Approval Date: 3/17/11	Expiration Date:
Title: Sr. Prod. Foreman		Conditions of Approval:	Attached <input type="checkbox"/>
E-mail Address: rragland@sdrge.com		Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:	
Date: April 29, 2010	Phone: (575) 392-9797	4/17/11	

* Attach Additional Sheets If Necessary

2KP-648