

RECEIVED JAN 06 2010  
CMMCL

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

30-015-31891

Release Notification and Corrective Action

NKMLW 1107640000

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Kanicia Carrillo
Address	550 W. Texas, Suite 100 Midland, TX 79701	Telephone No.	432-685-4332
Facility Name - Holder	CB 6&7	Facility Type-	Battery

Surface Owner	Federal	Mineral Owner		Lease No.	NMLC056551A
---------------	---------	---------------	--	-----------	-------------

SW1/4-NW1/4

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	17	17S	30E					Eddy

Driving directions to battery: From Loco Hills go North on CR217 .9 m - turn West .6 m - turn North .3 m - turn East .1 m to location  
Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE


Type of Release- Oil	Volume of Release-80 bbls	Volume Recovered- 30 bbls
Source of Release- Circulating Pump	Date and Hour of Occurrence- 12/22/09	Date and Hour of Discovery 12/22/09
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, Terry Gregston	
By Whom? Pat Ellis	Date and Hour 12/23/09 4:44pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
Circulating pump discharge piping failed. Piping was fixed.

Describe Area Affected and Cleanup Action Taken.\*  
Scraped battery pad(minimal contamination)-Top dressed pad w/clean material-picked 6" of contaminated top soil on edge of pad and hauled to environmental land fill.  
Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for your approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Kanicia Carrillo	Approved by District Supervisor: <u>Signed By Mike Bratcher</u>	
Title: Regulatory Analyst	Approval Date: 3/17/11	Expiration Date:
E-mail Address: kcarrillo@conchoresources.com	Conditions of Approval: attached <input type="checkbox"/>	
Date: 1/06/10 Phone: 432-685-4332	REMEDATION per OCD Rules and Guidelines. SUBMIT REMEDIATION PROPOSAL BY: 4/17/11	

\* Attach Additional Sheets If Necessary

2RP-646