

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

*nkmw 1102536284*

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Lime Rock Resources II-A, LP <i>277558</i>	Contact	Michael Barrett
Address	1111 Bagby St Suite 4600 Houston, Tx 77002	Telephone No.	575-623-8424
Facility Name	Condor 8 Fed #1H	Facility Type	Battery

Surface Owner	Richard Gateway	Mineral Owner	BLM	Lease No. API #	30-015-35829
---------------	-----------------	---------------	-----	-----------------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	8	18S	27E	1770'	FNL	2525'	FWL	Eddy

Latitude 32.76 Longitude 104.30

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	47 bbls	Volume Recovered	10bbls
Source of Release	Circulating Pump	Date and Hour of Occurrence	3-11-11 am	Date and Hour of Discovery	3-11-11 1:00pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher w/ OCD		
By Whom?	Michael Barrett w/ LRR	Date and Hour	3-11-11 @ 5:15pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

1" Line on circulation pump leaked. Filled & overflowed sump. Ran off pad and down low spot to lease road. Isolated leak.

Describe Area Affected and Cleanup Action Taken.\*

Packed dry soil w/ rock. P/U standing fluid and sprayed area w/ Micro Blaze.

RECEIVED

MAR 15 2011

NMOCD ARTESIA

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Michael Barrett</i>	OIL CONSERVATION DIVISION	
Printed Name: Michael Barrett	Approved by District Supervisor: <i>Mike Bratcher</i>	
Title: Production Supervisor	Approval Date: <i>3/14/11</i>	Expiration Date:
E-mail Address: <i>mbarrett@limerockresources.com</i>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3-14-11 Phone: 575-623-8424	REMEDATION per OCD Rules and Guidelines. <u>SUBMIT REMEDIATION PROPOSAL BY:</u>	

\* Attach Additional Sheets If Necessary

*4/16/11*

*2RP-641*