

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-36467

Release Notification and Corrective Action

AKMLW 1107652510

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	ELECTRA NORTH FEDERAL TANK BATTERY	Facility Type	Tank Battery

Surface Owner	Federal	Mineral Owner		Lease No.	NM 0467931
---------------	---------	---------------	--	-----------	------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	10	17S	30E					EDDY

Latitude 32 51.190 Longitude 103 57.540

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	160bbbls	Volume Recovered	145bbbls
Source of Release	Equalizer	Date and Hour of Occurrence	03/13/2010	Date and Hour of Discovery	03/13/2010
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher - OCD		
By Whom?	Josh Russo	Date and Hour	03/15/2010 4:59 p.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

The cause of the release was due to a plugged equalizer. The plugged equalizer has been repaired.

Describe Area Affected and Cleanup Action Taken.*

The entire release was fully contained inside the dike walls of the tank battery. 160bbbls of oil was initially released, and 145bbbls were recovered by a vacuum truck. The contaminated dirt and gravel has been removed from the spill area. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD/BLM for approval prior to any significant remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	
Printed Name:	Josh Russo
Title:	HSE Coordinator
E-mail Address:	jrusso@conchoresources.com
Date:	03/18/2010
Phone:	432-212-2399

* Attach Additional Sheets If Necessary

OIL CONSERVATION DIVISION

Approved by District Supervisor: 

Approval Date: 3/17/11 Expiration Date:

Conditions of Approval: Attached ☐

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:**

4/17/11

2RP-649