<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> District III
1000 Rio Brazos Road, Aztec, NM 87410

State of New Mexico Energy Minerals and Natural Resource RECEIVED

Form C-141 Revised October 10, 2003

Oil Conservation Division

NOV 1 8 2009

Submit 2 Copies to appropriate District Office in accordance

District IV				1220	South	i St. Franc	is Dr.		-		- 1	with Rule 116 on back	
1220 S. St. Francis Dr., Santa Fe, NM 87505			!	S	e, NM 875	NMO	NMOCD ARTESIA			side of form			
		4447	RATOI	on and Corr	ective A			nitial Repo		☐ Final Report			
Name of Company				1		Contact							
Yates Petro	leum Corp	oration	25575			<u>ijillo</u>							
Address 104 S. 4 TH S	Street				Telephone N 575-748-14								
Facility Na	API Number		Facility Type Order Number										
Greasewood		#2	1		Battery 2RP-								
Surface Ou	mor		Mineral (Junar					Longo	Ma			
Surface Owner State				State	Lease No. OG-783								
June OG-703													
Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County													
				Feet from the				om the	1	unty			
E 6 198 25E 2310					<u> </u>	North 990 West Eddy					dy		
Latitude N33.13240 Longitude W104 13323 NATURE OF RELEASE													
Type of Release						Volume of Release Volume R					Reco	vered	
Condensate						Less the 5				0			
Source of Release Well header						Date and Hour of Occurrence Date and Hour of Discovery 9/22/09 am 9/22/09 am						r of Discovery	
Was Immedia		If YES, To			· · ·),, <u>22</u> ,0, u							
	d Mike Bratcher - NMOCD/Artesia												
By Whom?	Date and Hour												
Amanda Truj Was a Water		11/12/2009 pm If YES, Volume Impacting the Watercourse.											
was a water		N/A											
If a Watercou	irse was Im		Yes ⊠ be Fully.*							***			
N/A Describe Cau	ise of Proble	em and Rama	lial Action	n Taken *	· · · · · · · · · · · · · · · · · · ·								
Describe Cause of Problem and Remedial Action Taken.* On 9/22/09 a crack in the bottom of a check valve released crude oil and produced water. It was an un-reportable quantity; however an internal report was													
generated. A	series of sm	all un-reporta	ble spills	have occurred over	er time a	t this location	. During						
				d of a at an NMO	CD app	roved facility.							
Describe Area Affected and Cleanup Action Taken.* The area is 15' x 15'. A dozer will scrape up the contaminated material and dispose of it at an approved facility. Soil will be tested for TPH, BTEX and Chlorides.													
Depth to G	round Wat	er: >100' (ap	prox. 300	', per New Mexic	co Offic	e of the State	Engine	er); Well	head P	rotection A	Area	: No; Distance to Surface	
				Based on site gro									
												to NMOCD rules and which may endanger	
												he operator of liability	
												face water, human health	
or the enviror federal, state,				tance of a C-141	report de	oes not relieve	the ope	erator of r	esponsi	bility for co	ompl	iance with any other	
rederal, state,	1	. /	ations.		T		OIL	CONS	ERV	ATION	DIZ	VISION	
Signature: Teciji W													
						La la prista de la							
Printed Name: Amanda Trujillo							Approved by District Supervisor Miles Bennus						
Title: Environmental Scientist						Approval Date: 4/4/11 Expiration Date:							
								7 - 7		_			
E-mail Addre	ss: atrujillo((a)yatespetrole	um.com		(Conditions of			~ Occ	Dulas = -		tached	
Date: Monday, November 16, 2009 Phone: 575-748-4310								-		Rules an	197		
Attach Additional Sheets If Necessary						Guidelines. SUBMIT REMEDIATION 2RP 695							
						PROP	DOAL B	™	1/			WIN AID	
								- 1/4	+	-			