

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
2040 South Pacheco  
Santa Fe, NM 87505

Form C-141  
Revised March 17, 1999

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

*nkms 1109628560*

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company:	Devon Energy Production LP	Contact <input type="checkbox"/>	Jerry Mathews
Address:	PO Box 250, Artesia, NM 88211	Telephone No. <input type="checkbox"/>	575-748-0161
Facility Name:	Laguna Salado 22 Fed #6H	Facility Type <input type="checkbox"/>	Oil Well, #30-015-37371

Surface Owner:	MOSAIC	Mineral Owner	Lease No. <input type="checkbox"/> NMNM-66425
----------------	--------	---------------	---

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	22	23S	29E	1172	North	2510	West	Eddy

NATURE OF RELEASE

Type of Release:	Produced Water	Volume of Release:	10 bbls	Volume Recovered <input type="checkbox"/> 0 bbls	
Source of Release:	Overflowed Frac Tanks	Date and Hour of Occurrence:	3/31/2011; 8:00 A.M.	Date and Hour of Discovery	3/31/2011; 10:25 A.M.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Eugene Abernathy with MOSAIC		
By Whom?	Jerry Mathews with Devon Energy	Date and Hour	3/31/2011; 10:25 A.M.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The flowback hand fell asleep and he was terminated.

Describe Area Affected and Cleanup Action Taken.\*

The area affected was a caliche road. MOSAIC requested we scratch the road surface and lay new caliche, which we did.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jerry Mathews</i>	OIL CONSERVATION DIVISION	
Printed Name: Jerry Mathews	Approved by <input type="checkbox"/> District Supervisor <i>Mike Brannon</i>	
Title: Completions Foreman	Approval Date: <i>4/6/11</i>	Expiration Date:
Date: 4/1/2011 Phone: 575-748-0161	Conditions of Approval: Remediation per OCD Rules & Guidelines. <b>SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:</b>	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

*5/10/11*

*2 RP 716*

RECEIVED

APR 05 2011

NMOCD ARTESIA