

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report **X** Final Report

NMCB 1111631331

Name of Company: Marshall & Winston, Inc.	Contact: Tom Brandt
Address: PO Box 50880, Midland, TX 79710-0880	Telephone No.: 432-684-6373
Facility Name: DUBLIN 23 FEDERAL NO. 1	Facility Type: Oil & Gas Wellsite NMOCD 2RP No.: 754

Surface Owner: Federal	Mineral Owner: Federal	LEASE No.: LC-069157 API No.: 30-015-34879
---------------------------	---------------------------	---

LOCATION OF RELEASE

Unit Letter O	Section 23	Township 22S	Range 28E	Feet from the 660	North/South Line South	Feet from the 1980	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude ____ Longitude ____

NATURE OF RELEASE

Type of Release: Produced water from accidental truck discharge	Volume of Release: Unauthorized Discharge - Unknown	Volume Recovered: None (sandy/rocky area quickly absorbed)
Source of Release: Leaking valve on the southern most load line while VMJ transport truck was loading out.	Date and Hour of Occurrence: Unknown	Date and Hour of Discovery: BLM NWO 1 December 2010
Was Immediate Notice Given? ASAP due to documentation issues. Operator not aware that this discharge was reportable until recent field work began. This changed status from an NR. Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD (Mike Bratcher) 7 December 2010 via letter as an NR at that time	
By Whom? BLM	Date and Hour: Unknown based on issuance of NWO on 11/28/2010	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		RECEIVED APR 21 2011 NMOCD ARTESIA
Describe Cause of Problem and Remedial Action Taken.* Since the produced water discharge had occurred at an unknown time, all discharged liquid had soaked into the impacted areas both offsite and into the side of the pad adjacent to the southern most water tank. A backhoe was contracted to begin removing the contaminated soils and haul these to disposal as soon as possible to prevent further vertical and horizontal absorption. Samples were taken to establish the discharge baseline for excavation purposes.		
Describe Area Affected and Cleanup Action Taken.* Cleanup was conducted as delineated in the CAP pursuant to NMOCD regulatory mandates. Sampling defined the extent of the spill area and remediation was conducted accordingly following 10 February 2011 onsite by BLM and NMOCD. See attached laboratory documents for details and FRR.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment.		
Signature: <i>Tom M. Brandt</i>	OIL CONSERVATION DIVISION	
Printed Name: Tom M. Brandt	Approved by District Supervisor: <i>Mike Bratcher</i>	
Title: President	Approval Date: <i>4/26/2011</i>	Expiration Date: <i>NA</i>
E-mail Address: <u>tbrandt@mar-win.com</u>	Conditions of Approval: <i>NA</i>	Attached <input type="checkbox"/>
Date: 29 March 2011 Phone: 432-684-6373		

* Attach Additional Sheets If Necessary

2RP-754