<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II
1301 W. Grand Avenue, Artesia, NM 88210 District III
1000 Rio Brazos Road, Aztec, NM 87410 **District IV**

* Attach Additional Sheets If Necessary

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr.

Revised October 10, 2003

Form C-141

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back

2RP-774

1220 S. St. Fran	icis Dr., Sant	5	Santa Fe, NM 87505						47.5°		side of form	
30-015-	3392	9	Rel	ease Notific				ction			paker lake ere	
nMLB/1/2542397						OPERATOR [al Report		Final Repo
Name of Company BOPCO, L.P. 260737						Contact Tony Savoie						
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220						Telephone No. 432-556-8730						
Facility Na	me Poker I	Lake Unit #2			Facility Type E&P SWB							
Surface Owner Federal Mineral Owner						Federal			Lease No.			
				LOCA	ATIO	N OF REI	LEASE					
Unit Letter Section Township Range 30 24S 30E Feet from the No.					North	th/South Line Feet from the			East/West Line County Eddy			
Latitude_N 32.18191 Longitude W 103.91429												
NATURE OF RELEASE												
Type of Rele					Volume of Release: 50 bbls produced water.			Volume Recovered: none				
Source of Re	lease: 2' po	ly line connec	ater transfer pump	p.	Date and Hour of Occurrence 4/19/11, Hour unknown			Date and Hour of Discovery 4/19/11 at 7:29 p.m.				
Was Immedia	ate Notice (No □ Not Re	equired	If YES, To Whom?							
By Whom?						Date and Hour						
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.						
If a Watercou	ırse was Im	pacted, Descri	be Fully.*						DE	CEIV	/En	, 7
i						111		كسا سيا				
			MAY 0				IAY 04 2	2011				
Describe Cause of Problem and Remedial Action Taken.* A 2" poly line failed where it was connected to a water transfer pump. The pump was shut down causing the flow of Water to stop. The poly line was repaired later that evening.												
width where i area on 4/20/ into the wash to the wash ar	l water trave it traveled a I I and agree area. On 4/2 ea to captur	eled down a le opproximately ed to wash the 25/11 approximater what water	ase road for the second	or approximately efore dumping intured down with from the balls of fresh water at the end. The	o anothesh wat ter was site is	er wash area, ter and use a vasued to rinse pending revie	traveled approxin acuum truck to ca down the road an w by the NMOCI	nately 30 pture the d gully, a D and BI	ft. and sto crinsed wa a 2" poly l LM for Clo	opped. The E ster at the po ine was laid osure.	BLM re- int whe across	viewed the are it entered the pasture
regulations al public health should their o	l operators a or the environer perations had ment. In ac	are required to conment. The a live failed to a dittion, NMO	report and acceptance dequately CD accept	is true and compl d/or file certain re e of a C-141 repor investigate and re ance of a C-141 r	lease not the contract the cont	otifications an e NMOCD ma e contamination	d perform correct rked as "Final Re on that pose a thre	tive action port" do cat to gro	ons for rele es not relie und water,	eases which in the contract was a surface wat	may end ator of l er, hun	danger liability nan health
Signature:	Tony Savo	, Sa			Approved by Distingth Supervisor.							
Title: Waste N	/lgmt.& Rer	nediation Spe			Approval Date: 5/5/20/1 Expiration Date:							
E-mail Address: TASavoie@BassPet.com						Conditions of Approval: Attached						
Date: 5/3/11	anal Ch	e If Nooses	P	hone:432-556-87	30 G	Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION						