

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other Instructions on
reverse side)

copy to SF
Form approved
Budget Bureau No. 42 R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 2357

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

1. OIL WELL GAS WELL OTHER

JUN 14 1977

2. NAME OF OPERATOR
Yates Petroleum Corporation

3. ADDRESS OF OPERATOR
207 South Fourth Street - Artesia, NM 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

330' FNL & 1650' FEL of Section 31-6S-26E

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal "HJ"

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Und Linda (S.A.)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec 31-6S-26E

Unit B NMPM

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3670' GR

12. COUNTY OR PARISH

Chaves

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other) Spud

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded 12 1/4" hole at 4:00 PM 5-20-77. Drilled to 257' and ran 7 joints of 8-5/8" 20# X-42 (257') of casing set at 257'. Cemented w/150 sacks of Class "C" 4% CaCl. Cement circulated 20 sacks to surface. PD 12:30 AM 5-21-77. WOC 18 hours, nipped up, reduced hole to 6 1/4", drilled plug and tested to 600#. OK. Resumed drilling.

RECEIVED

JUN 09 1977

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED Christine Johnson TITLE Geological Secretary DATE June 9, 1977

(This space for Federal or State office use)

APPROVED BY Lee D. Lars TITLE ACTING DISTRICT ENGINEER DATE JUN 10 1977
CONDITIONS OF APPROVAL, IF ANY: