

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well  gas well  other

2. NAME OF OPERATOR  
Yates Petroleum Corporation ✓

3. ADDRESS OF OPERATOR  
207 South 4th St., Artesia, NM 88210

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 1980' FWL & 1100' FNL  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF <input type="checkbox"/>	<input checked="" type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE <input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES <input type="checkbox"/>	<input type="checkbox"/>
ABANDON* <input type="checkbox"/>	<input type="checkbox"/>
(other) <input type="checkbox"/>	

RECEIVED  
JUL 8 1981  
U.S. GEOLOGICAL SURVEY

NOTE: Report results of multiple completion or zone change on Form 9-330.

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Spudded a 17-1/2" hole at 9:15 AM 6-27-81. Ran 16 jts. of 13-3/8" 54.50# (729') of casing set at 729'. 1-regular pattern guide shoe at 729'. Flapper float at 683'. Cemented w/900 sacks Class "C" 4% CaCl. PD 9:30 AM 6-28-81. Bumped plug to 450 psi, released pressure and float held okay. Cement circulated 50 sacks. WOC 12 hrs. Reduced hole to 7-7/8". Drilled plug and resumed drilling.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Jeanette Goodlett TITLE Engineering Sect. DATE 7-7-81

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD  
(This space for Federal or State office use)  
ROGER A. CHAPMAN  
JUL 9 1981  
U.S. GEOLOGICAL SURVEY  
ROSWEEL, NEW MEXICO  
See Instructions on Reverse Side

5. LEASE  
NM-36409

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
McClellan "MB" Federal

9. WELL NO.  
3

10. FIELD OR WILDCAT NAME  
Undesignated

11. SEC., T., R., M. OR BLK. AND SURVEY OR AREA Unit C  
Sec. 31-T5S-R25E

12. COUNTY OR PARISH | 13. STATE  
Chaves | NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)  
3810' GL

RECEIVED

JUL 13 1981

O. C. D.  
ARTESIA, OFFICE