

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Artesia NM 88216

SUBMIT IN TRIPPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 32323

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Fivemile Tank Federal

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

ABO Wildcat

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 9-6S-23E

12. COUNTY OR PARISH 13. STATE

Chaves N.M.

1.

OIL WELL GAS WELL OTHER Drilling well

2. NAME OF OPERATOR

TRANSWESTERN GAS SUPPLY COMPANY

3. ADDRESS OF OPERATOR

P.O. Box 2521, Houston, TX 77001

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)

At surface
1980'/S 1980'/E Sec. 9-6S-23E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4198' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
(Other) <input type="checkbox"/>	


(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Unable to recover fish.
Permanently abandoned well by filling hole from top of fish at 832' to the surface with cement, 1025 sx.
Plugging was completed on January 23, 1982 after obtaining oral approval from U.S.G.S.

Abandonment marker will not be installed due to proximity to the No.2-Y well which will be drilled 25' south of this well.

Location will be cleaned and leveled when No.2-Y is completed.



OIL & GAS
U.S. GEOLOGICAL SURVEY
LOSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

JERRY W. LONG

TITLE Agent

DATE January 30, 1982

(This space for Federal or State office use)

APPROVED BY

PETER W. CHESTER

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

NOV 4 1982

FOR

JAMES A. GILLHAM *See Instructions on Reverse Side
DISTRICT SUPERVISOR