

RECEIVED

NEW MEXICO OIL CONSERVATION COMMISSION

OCT 17 1960 FORM C-103 (Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

O. O. O. ARTESIA, OFFICE

Name of Company **Kersey & Company** Address **Box 305, Artesia, New Mexico**

Lease **A.S.U.** Well No. **A-1** Unit Letter **M** Section **2** Township **17S** Range **28E**

Date Work Performed Pool **Red Lake** County **Eddy**

THIS IS A REPORT OF: (Check appropriate block)

- Beginning Drilling Operations
- Casing Test and Cement Job
- Other (Explain):
- Plugging
- Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Went in old hole - Cleaned out to T.D. 1691'

Perforated zones 1644 - 1654; 1658 - 1664; 2 shots/foot. No debris gun. pumped into formation - pressure broke at 2800#. Pumped in 40,000 gallons slick water with 40,000 # 20-40 sand. Treating pressure 2100#. Pressure after shut in 5 minutes 1000#. Used 30 bbls. of water for flush.

Perforated gas zones 1597 - 1617' 2 shots/foot.

Witnessed by Position Company

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev. T D P B T D Producing Interval Completion Date

Tubing Diameter Tubing Depth Oil String Diameter Oil String Depth

Perforated Interval(s)

Open Hole Interval Producing Formation(s)

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by *M.L. Armstrong*

Name *Harold Kersey*

Title

Position **Owner**

Date

Company **Kersey & Company**

OIL CONSERVATION COMMISSION
ARTESIA DISTRICT OFFICE

No. Copies Received 4

DISTRIBUTION	
	NO. COPIES
OPERATOR	2
SANTA FE	1
PRODUCTION OFFICE	
STATE LAND OFFICE	
U. S. G. S.	
TRANSPORTER	
FILE	1
BUREAU OF MINES	