

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

CLSF

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-G for such proposals.)

1. oil well  gas well  other

2. NAME OF OPERATOR  
JDR, Ltd. /

3. ADDRESS OF OPERATOR  
Box 648, Artesia, N.M. 88210

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 330 W 330 N 19 17 28  
AT TOP PROD. INTERVAL: Same  
AT TOTAL DEPTH: Same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

5. LEASE  
LC 050349 A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME RECEIVED

7. UNIT AGREEMENT NAME  
APR 14 1982

8. FARM OR LEASE NAME  
Brooks O. C. D.

9. WELL NO.  
16 ARTESIA, OFFICE

10. FIELD OR WILDCAT NAME  
EMPIRE Y-SR

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
19 17 28

12. COUNTY OR PARISH 13. STATE  
Eddy N.M.

14. API NO.


15. ELEVATIONS (SHOW DF, KDB, AND WD)  
3576 Gr.

REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF <input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	<input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	<input checked="" type="checkbox"/>
MULTIPLE COMPLETE <input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES <input type="checkbox"/>	<input type="checkbox"/>
ABANDON* <input type="checkbox"/>	<input type="checkbox"/>
(other) <input type="checkbox"/>	<input type="checkbox"/>

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Dug out top of casing to approximately 16' and cut off below 5½" liner.  
Welded in good section of 7" pipe. Well now is 7" from surface to 530'  
cleaned well out and put back on production.



Subsurface Safety Valve: Manu. and Type

Set @

18. I hereby certify that the foregoing is true and correct

SIGNED Dalton Bell TITLE General Partner DATE April 6, 1982

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_ ACCEPTED FOR RECORD

CONDITIONS OF APPROVAL, IF ANY:

APR 13 1982  
U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEX

\*See Instructions on Reverse Side