

DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well  gas well  other
2. NAME OF OPERATOR  
Kersey & Company
3. ADDRESS OF OPERATOR  
P.O. Box 316, Artesia, NM 88211-0316
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 16 50/N & 1980/E  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

RECEIVED  
MAR 13 1992

O. C. D.  
ARTESIA OFFICE

- |                          |                                     |                       |                          |
|--------------------------|-------------------------------------|-----------------------|--------------------------|
| REQUEST FOR APPROVAL TO: |                                     | SUBSEQUENT REPORT OF: |                          |
| TEST WATER SHUT-OFF      | <input type="checkbox"/>            |                       | <input type="checkbox"/> |
| FRACTURE TREAT           | <input type="checkbox"/>            |                       | <input type="checkbox"/> |
| SHOOT OR ACIDIZE         | <input type="checkbox"/>            |                       | <input type="checkbox"/> |
| REPAIR WELL              | <input type="checkbox"/>            |                       | <input type="checkbox"/> |
| PULL OR ALTER CASING     | <input type="checkbox"/>            |                       | <input type="checkbox"/> |
| MULTIPLE COMPLETE        | <input type="checkbox"/>            |                       | <input type="checkbox"/> |
| CHANGE ZONES             | <input type="checkbox"/>            |                       | <input type="checkbox"/> |
| ABANDON*                 | <input checked="" type="checkbox"/> |                       | <input type="checkbox"/> |
| (other)                  |                                     |                       |                          |

LC-028456-A  
6. IF INDIAN, LOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME  
Red Lake Premier Sand Unit
8. FARM OR LEASE NAME  
Stephens TR 13
9. WELL NO.  
# 3
10. FIELD OR WILDCAT NAME  
Red Lake Queen-Grayburg
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
SE/4 NE4 Sec 20 T17S R28E
12. COUNTY OR PARISH  
Eddy
13. STATE  
NM
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1. Spot 100' cement plug between 1819-1919'
2. Perforate casing at 1250'
3. Spot 100' cement in and out of 5 1/2" casing.
4. Perforate 5 1/2" casing @ 500'
5. 100' Plug in and out of casing.
6. Surface plug and Marker - 50' of cement in casing.

Subsurface Safety Valve: Manu. and Type

Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Harold Kersey TITLE Co-Owner

DATE Mar. 14, 1991

(This space for Federal or State office use)

APPROVED BY David A. Glass TITLE \_\_\_\_\_

DATE 3-12-92

CONDITIONS OF APPROVAL, IF ANY: