

NEW MEXICO OIL CONSERVATION COMMISSION
Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Report by Checking Below

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON RESULT OF TEST OF CASING SHUT-OFF	<input checked="" type="checkbox"/>	REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL		REPORT ON RECOMPLETION OPERATION		REPORT ON (Other)	

November 24, 1953

Dallas, Texas

(Date)

(Place)

Following is a report on the work done and the results obtained under the heading noted above at the

San Juan Drilling Company

San Juan State

(Company or Operator)

(Lease)

Hall & Stewart Drilling Company, Inc.

Well No. B-1 in the SW 1/4 SW 1/4 of Sec. 28

(Contractor)

T. 17S, R. 28E, NMPM, Wildcat Pool, Eddy County.

October 22 - 24, 1953

The Dates of this work were as follows:

Notice of intention to do the work (was) (was not) submitted on Form C-102 on....., 19....., (Cross out incorrect words)

and approval of the proposed plan (was) (was not) obtained.

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Set 13-3/8" surface casing at 599'. Cemented with 450 sacks 4 1/2 gal cement and 150 sacks regular neat cement using Halliburton method. Cement circulated to surface and allowed to set 48 hours.

Witnessed by E. W. Adams San Juan Drilling Company Agent
(Name) (Company) (Title)

Approved: OIL CONSERVATION COMMISSION
P. A. Johnson
(Name)
(Title) (Date)

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name W. Smith
Position Agent
Representing San Juan Drilling Company
Address 823 Corrigan Tower Bldg., Dallas, Texas