

Check table 52

(SUBMIT IN TRIPLICATE)

Land Office _____


Lease No. **060325**

Unit **1**

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

ILLEGIBLE

SUNDRY NOTICES AND REPORTS ON WELLS



NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	XX	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 13, 1963

Well No. **Leonard 2** is located **1900** ft. from **IN** line and **660** ft. from **E** line of sec. **33**

NE/4 SE/4 Sec. 33 **166** **30E** **N.M.P.M.**

(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Square Lake **Eddy** **New Mexico**

(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **3734** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We propose to rig up cable tools and clean out hole with 4" tools to 2970, run tubing, rods and put well on production.

RECEIVED
Nov 18 1963
M. D. C.
ARTESIA OFFICE

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **NEWMONT OIL COMPANY**

Address **ROWLEY BUILDING,**
ARTESIA, NEW MEXICO

By **H. J. LEDBETTER**

Title **District Superintendent**