

45F

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Artesia, NM 88210

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well gas well other

2. NAME OF OPERATOR
The Superior Oil Company

3. ADDRESS OF OPERATOR
P. O. Box 3901 Midland, Texas 79702

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1480' FNL, 660' FWL, Section 5
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH: Same

5. LEASE
NM-15439

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME RECEIVED

8. FARM OR LEASE NAME
Star Federal OCT 18 1982

9. WELL NO.
1 O.C.D.

10. FIELD OR WILDCAT NAME OFFICE
Wildcat (Morrow)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Section 5, T16S, R29E

12. COUNTY OR PARISH | 13. STATE
Eddy County | New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3605.8' GR

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>		<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>		<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>		<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>		<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>		<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>		<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>		<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>		<input type="checkbox"/>
(other) Weekly Drilling Report			

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

7-17-82 Drld to 8836'.
 7-18-82 Drld to 9004'.
 7-19-82 Circ samples. Svy 1 3/4° @ 9040' & POH. Chg. bits. TIH. No fill.
 Drld to 9097'.
 7-20-82 Drld to 9245'.
 7-21-82 Drld to 9405'. Survey 3° @ 9460', POH w/Bit #15. TIH w/Bit #16.
 Wshd 30' to btm, no fill. Drld to 9490'.
 7-23-82 Drld to 9613'.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED G. E. Tate TITLE Prod. Supt. DATE July 26, 1982

ACCEPTED FOR RECORD (This space for Federal or State office use)
 (ORIG. SGD.) DAVID R. GLASS
 APPROVED BY _____ DATE _____
 CONDITIONS OF APPROVAL, IF ANY:
 OCT 15 1982
 U.S. GEOLOGICAL SURVEY
 ROSWELL, NEW MEXICO
 *See Instructions on Reverse Side

RECEIVED
JUL 20 1982