

RECEIVED
AUG 10 1951
Oil Cons. Comm.
Artesia Office

(SUBMIT IN TRIPLICATE)

**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**

Land Office Las Cruces
Lease No. 028936 D
Unit Well 10-D J

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 8th, 19 51

Well No. 11-D is located 210 ft. from N line and 210 ft. from E line of sec. 31

11-D (4 Sec. and 400 ft. No.) 31 (Twp.) 30 (Range) N. M. (State or Territory)

Artesia (Field) Lady (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We sent last notice of intention to drill on Well 10-D, approved at the United States Geological Survey in Artesia, New Mexico on August 2, 1951 by John A. Frost. This well is not Well 10-D it is Well 11-D. Please change your files accordingly.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Heland Rich Well
Address Box 398
Los Alamos
New Mexico
By J. L. Brice
Title Superintendent